

MOTORCYCLE ACCESSORIES | SERVICE CENTRE MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

: 26/08/2022

: RAYMOND

POLICY NO. : MC/00914057/01

QUOTATION

CLAIM NO. : 11994

NO. : 41509

DATE

FROM

AIG ASIA PACIFIC INSURANCE PTE LTD CHARTIS BUILDING 78 SHENTON WAY #07-16

SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO.
MAKE/MODEL

Customer:

: FBK1698Z : YAM / YBR125

(Page 1 of 4)

					` 0 ,
<u>S/N</u>	Description	<u>Action</u>	<u>Qty</u>	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561 - (REPORTED BY MECHANIC)	Repair	1.00	\$380.00	380.00
2	AXLE WHEEL FRONT P/N: 25363 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
3	BAR HANDLE P/N: 42062 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
4	BEARING 6202-DDUCM (NSK) P/N: 40216 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28.00
5	BRACKET FOOTREST LH P/N: 25346 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
6	BRACKET MUDGUARD FRONT P/N: 46221 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
7	BRACKET UNDER FORK P/N: 27458 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$180.00	180.00
8	CABLE CLUTCH P/N: 44111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
9	CABLE SPEEDOMETER P/N: 50366 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00





<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	Amount
10	CABLE THROTTLE 1	REPLACE	1.00	\$22.00	22.00
	P/N: 43817 - (REPORTED BY MECHANIC)				
11	CABLE THROTTLE 2	REPLACE	1.00	\$24.00	24.00
	P/N: 43812 - (REPORTED BY MECHANIC)				
12	CALIPER BRAKE FRONT ASSY	REPLACE	1.00	\$390.00	390.00
	P/N: 45878				
	- (REPORTED BY MECHANIC)			4050.00	250.00
13	CAMERA (V_SYS) M6 (WIFI VERSION)	REPLACE	1.00	\$350.00	350.00
	P/N: 56377 - (REPORTED BY MECHANIC)				
14	COVER SIDE LH (BLACK)	REPLACE	1.00	\$96.00	96.00
1 7	P/N: 50007				
	- (REPORTED BY MECHANIC)				
15	COVER SIDE RH (BLACK)	REPLACE	1.00	\$96.00	96.00
	P/N: 53724				
	- (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	77.00
16	COVER TAIL LH (RED) P/N: 45536	NEFLACE	1.00	φ11.00	77.00
	- (REPORTED BY MECHANIC)				
17	COVER TANK SIDE LH (BLACK)	REPLACE	1.00	\$96.00	96.00
	P/N: 54458				
	- (REPORTED BY MECHANIC)			***	00.0
18	COVER TANK SIDE RH (BLACK)	REPLACE	1.00	\$96.00	96.00
	P/N: 54477 - (REPORTED BY MECHANIC)				
19	COWLING FRONT (RED)	REPLACE	1.00	\$133.00	133.0
10	P/N: 52897				
	- (REPORTED BY MECHANIC)				
20	CRASH BAR	REPLACE	1.00	\$203.00	203.0
	P/N: 35878				
21	- (REPORTED BY MECHANIC) CROWN HANDLE	REPLACE	1.00	\$75.00	75.0
۷ ۱	P/N: 28100		,,,,,	,	
	- (REPORTED BY MECHANIC)				
22	FOOTREST REAR ASSY LH	REPLACE	1.00	\$15.00	15.0
	P/N: 25348				
	- (REPORTED BY MECHANIC)	REPLACE	1.00	\$624.00	624.0
23	FORK FRONT ASSY LH P/N: 45155	THE ENOL	1.00	ψ02-1.00	02 //0
	- (REPORTED BY MECHANIC)				
24	FORK FRONT ASSY RH	REPLACE	1.00	\$624.00	624.0
	P/N: 45154 - (REPORTED BY MECHANIC)				



<u> </u>	Description	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	Amount
25	GASKET EXHAUST PIPE	REPLACE	1.00	\$5.00	5.00
	P/N: 21453 - (REPORTED BY MECHANIC)				
26	HEADLAMP ASSY	REPLACE	1.00	\$105.00	105.00
	P/N: 43129 - (REPORTED BY MECHANIC)				
27	LABOUR	Supply/Install	16.00	\$63.00	1,008.00
	P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.				
28	LAMP SIGNAL FRONT LH	REPLACE	1.00	\$21.00	21.00
	P/N: 43433 - (REPORTED BY MECHANIC)				
29	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$21.00	21.00
	P/N: 43432 - (REPORTED BY MECHANIC)				
30	LAMP SIGNAL REAR LH	REPLACE	1.00	\$21.00	21.00
	P/N: 44190 - (REPORTED BY MECHANIC)				
31	LEVER CLUTCH	REPLACE	1.00	\$19.00	19.00
	P/N: 52644 - (REPORTED BY MECHANIC)				
32	METER ASSY	REPLACE	1.00	\$264.00	264.00
	P/N: 42063				
20	- (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	280.00
33	METER IU (12V) NEW MODEL P/N: 34351	NEI LAGE	1.00	Ψ200.00	200.00
	- (REPORTED BY MECHANIC)				
34	MID O-RING	REPLACE	1.00	\$3.00	3.00
	P/N: 18587				
	- (REPORTED BY MECHANIC)				
35	MIRROR LH	REPLACE	1.00	\$35.00	35.00
	P/N: 58099 - (REPORTED BY MECHANIC)				
36	MUDGUARD FRONT (RED)	REPLACE	1.00	\$49.00	49.00
,0	P/N: 42220		1100	¥ 15155	
	- (REPORTED BY MECHANIC)				
37	PIPE EXHAUST ASSY	REPLACE	1.00	\$630.00	630.00
	P/N: 26600 - (REPORTED BY MECHANIC)				
38	PLATE DISC BRAKE FRONT	REPLACE	1.00	\$193.00	193.00
	P/N: 46052 - (REPORTED BY MECHANIC)				
39	PLATE FRONT COWLING P/N: 46220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00





S/N	<u>Description</u>	<u>Action</u>	<u>Qty</u>	Unit Price	<u>Amount</u>
40	RUBBER FOOTREST FRONT	REPLACE	1.00	\$14.00	14.00
	P/N: 26136				
	- (REPORTED BY MECHANIC)				
41	STAY HEADLAMP	REPLACE	1.00	\$68.00	68.00
	P/N: 45750				
	- (REPORTED BY MECHANIC)				0.5.00
42	STEERING CONE SET	REPLACE	1.00	\$65.00	65.00
	P/N: 41793				
	- (REPORTED BY MECHANIC)		0.00	# 40.00	22.00
43	STICKER (MCDONALDS) SIDE COVER / WINDS	HEILD REPLACE	2.00	\$16.00	32.00
	P/N: 56222				
	- (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
44	STICKER (MCDONALDS) WINDSHIELD V2	REPLACE	1.00	φ10.00	10.00
	P/N: 56223 - (REPORTED BY MECHANIC)				
45	•	REPLACE	1.00	\$19.00	19.00
45	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT		1.00	Ψ10.00	
	P/N: 32921				
	- (REPORTED BY MECHANIC)				
46	TANK FUEL (RED)	REPLACE	1.00	\$441.00	441.00
	P/N: 46240				
	- (REPORTED BY MECHANIC)				
47	TRANSPORT CHARGES		1.00	\$56.00	56.00
	P/N: 07169				
	- BIKE TOWED BACK TO BHH				
48	VALVE RIM	REPLACE	1.00	\$13.00	13.00
	P/N: 27762				
	- (REPORTED BY MECHANIC)				
		SUB TOTAL			\$7,080.00
		GST @ 7 %			\$495.60
		GRAND TOTAL (SO	GD)		\$7,575.60
			•		-

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





Vehicle Details

Vehicle No.

Make / Model

FBK1698Z

YAMAHA / YBR125

Vehicle Type:

P00 - Passenger

Motorcycle/Autocycle/Moped

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Normal

Chassis No.:

LBPKE1789E0028774

Propellant:

Petrol

Engine No.:

E3J2E016944

Motor No.:

Engine Capacity:

124 cc

Power Rating:

Maximum Power Output:

320 kg

114 kg

Year Of Manufacture:

Maximum Laden Weight:

Original Registration Date:

Unladen Weight:

2014

13 Apr 2015

Lifespan Expiry Date:

COE Category:

D - Motorcycle

Quota Premium:

COE Expiry Date:

\$4,800.00

12 Apr 2025

Road Tax Expiry Date:

PARF Eligibility Expiry Date:

12 Oct 2022

-

Inspection Due Date:

Intended Transfer Date:

12 Apr 2023

02 Sep 2022

CO2 Emission:

CEV/VES Rebate Utilised Amount:

SA1D228U0002-01 / Ajax Mars Pte Ltd ENTRY DATE & TIME: 30/08/2022 20:34 (SGT) SUBMITTED BY: Aizam VERSION: 2 (31/08/2022 18:51 (SGT))



SINGAPORE ACCIDENT STATEMENT

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- of the issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT	I STATEMENT
Date of Submission Reported by Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	30/08/2022 20:34 (SGT) Driver 23/08/2022 18:30 (SGT) Singapore BUKIT TIMAH ROAD Singapore
DETAILS OF	OWN VEHICLE
Vehicle Registration Number	FBK1698Z
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes BAN HOCK HIN CO PTE LTD 1XXXXX288K workshop@bhh.com.sg (Phone) +65-62816520
VEHICLE PARTICULARS	
Manufacturer Model Variant	Yamaha YBR125
Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission	Employment No - Claiming third party Motorcycle Manual

125

INSURANCE COMPANY

Direct Asia Insurance (Singapore) Pte Ltd Name of Insurance Company MC/00914057 Policy Number / Cover Note Number

DRIVER

ZAIFUL BIN DZAKARIA Name of Driver GXXXX431K Work Permit No Date Of Birth 12/11/1979 Outdoor Occupation

Date Of Driving Pass 22/09/2015 Driving experience
Gender 6 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-85236264 Alt. Phone Number Email Address workshop@bhh.com.sg Address NA Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Side Swipe Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Nο Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Bukit Timah Neighbourhood Police Centre Police Station Name (Phone) +65-18004629999 Police Station Phone No Alt. Police Station Phone No (Fax) +65-64628933 1 Duke Road Singapore 268914 Police Station Address Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO POLICE REPORT: T/20220830/2074 LODGED AT BUKIT TIMAH NPC On 23/08/2022, around 6.30pm, I was on my way to make a delivery for McDonald's to Namly Gardens on my motorcycle. As I was turning into Namly Avenue from Bukit Timah Road, I suddenly felt an impact on my motorcycle and I fell onto the ground. A silver Mercedes car had collided into my motorcycle. However, I was unsure of where the car came from and how the accident occurred as it happened too quickly. I then called for police and an officer attended to me. I was then given a case card with incident number E/20220823/0098. Subsequently, I was convey by ambulance to Tan Tock Seng Hospital and given a 1 month MC for my injuries. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera?

DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number	SFG1333A
Vehicle Manufacturer	Mercedes
Vehicle Model	/ E200 EXCLUSIVE (R18 LED)
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Private car
Name of Driver	-
Contact Number	_
Address	-
Address complement	_
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender	ZAIFUL BIN DZAKARIA Male
Phone No	(Phone) +65-85236264
Address	_
Address Complement	-
Post Code	-
Approximate Age Years Old	42
Injuries Sustained	Fractured on right hand
Injured person in which vehicle?	FBK1698Z
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

- 1. Pease report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

(a) My Insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the maling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mali packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

	ZAILUL	Witnessed By Reporting Officer Muhammad Sumardi Bin Mohd Affand
Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
Sketch Plan	Karananyan walioni na makanaya na karana mana mata mata mata mata mata mata m	en with entry right only right from A. A. Effet e
REFER TO ATTACHE	D ACCIDENT DIAGRAM	



Describe Circumstances of the	he Accident	
Refer as police	e reports (T/20220830/2	074)
		A de la constanta de la consta
		Anno Anno Anno Anno Anno Anno Anno Anno
		Par per solution for Advantage
Declaration		
I'We declare the foregoing particular	rs are true in every respect.	
	Swienr	Witnessed By Reporting Officer Muhammad Sumardi Bin Mohd Alfandi
Policyholder's Signature / Date & Time	Oriver's Signature (if driver is not the policyholder) / Oate & Time	Witnessed by Reporting Centre Personnel



	Police Station Of Origin Buikt Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No. 1800-4629999 REPORT OF A TRAFFIC ACCIDENT	R	1 sc3 sport No. 172022063072074	
	Date/Time Report Made 30/08/2022 16:04	Vide Report No.: E/20220823/0098	Station Diary No	
	Informant's Particulars	Address:		VW
	ZAIFUL BIN DZAKARIA ID Type / ID No.: FIN NO / G6949431K	Home/Office	s: 85236264	
	Nationality:	Email: zaifuldzakaria1279@gmail.com :: Type of Informant:		$\neg V /\!\!/ \!\!/$
W .	Sex. Age: Date of Birth Male 42 12/11/1979		ution / School Name.	- W
	Race: Malay	Driving Licence Information:	a of Expiry:	
	Occupation DELIVERY RIDER	Class: 28 Dat	O CAPITY	W
	U - of the Accid	ent	Type of Location:	₩
	General Information of the Accident Injury Type of Conveyed By Accident:	Ambulance Drink Date/Time of Accident: 23/08/2022	T-Junction	100
	Location:			
	BUKIT TIMAH ROAD		11 -11	
	- There	Road Surface:	Road Speed Limit 70 Km/h	
	Weather: Clear	Traffic Control:	Traffic Volume: Light	1
	Traffic Flow: Two Way	Not Controlled	Anyone conveyed by ambulance:	
	Type of Collision. Between Moving Vehicles - Hea	d To Side	Yes	
	Details of Vehicle Involved	Model Color	Condition No of Passen	ger
	Vehicle No. Type M. FBK1698Z Motorcycle	ake Mcdel	Slightly 0 Damaged	
	FBRIDOC			\Box
	Details of Person Involved		rian Crossing: NA	
	Any Pedestrian Involved: No No. of Pedestrians Injured: NIL	Use of Pedesi	Half Closuring.	
	No. 017 cocours			
	No. of Pedesinans injures.			

. .



Police Station Of Origin: Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 Tel No: 1800-4629999




Report No. 1/20220839/2074

CONTINUATION OF REPORT

Rider	77.57		ID No.	1	G6949431K
Name	ZAIFUL BIN DZAKARIA				
			Contac	t No.	85236264
Related Vehicle	NIL				- 40
		To the same	Class o)f	Class: 2B Date of Expiry: NII
Hospital/Clinic	NIL		Driving	The second second second	Date of rybing.
			Licenc	e&	
			Expiry		
		Date Disc	harge	NIL	
Date Treatment	NIL ted Medical Leave NIL	Degree of	Injury	INIL	

Brief Details.
On 23/08/2022, around 6.30pm, I was on my way to make a delivery for McDonald's to Namly Gardens on my motorcycle. As I was turning into Namly Avenue from Bukit Timah Road, I suddenly felt an impact on my motorcycle and I fell onto the ground. A silver Mercedes car had collided into my motorcycle. On my motorcycle and I fell onto the ground. A silver Mercedes car had collided into my motorcycle. However, I was unsure of where the car came from and how the accident occurred as it happened too quickly. I then called for police and an officer attended to me. I was then given a case card with incident number E/20220823/0098. Subsequently, I was conveyed by ambulance to Tan Tock Seng Hospital and given a 1 month MC for my injuries.





IMPORTANT NOTE: Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report.

		ADDE	NDUM	
PARTICULARS OF PERSON MAKING THE AMENDMEN		IENTS:		
Original	Report No:	SA1D228U0002	Vehicle Registration	on No: FBK1698Z
		ZAIFUL BIN DZAKARIA		
		nricj. gbirle Owner) (*) Please delete		gradulate/harcoccondization/predictation/enterprised-contention/contention
				0 1
				Singapore (36264
Contact	(Tel):		Mobile No.:	30204
Date of	Accident:	23/08/2022	Time of Accident:	18:30 (SGT)
Place of	Accident	BUKIT TIMAH ROAD		
riace or	Accident	y: Direct Asia Insurance	(Singanore) Pte Ltd	
		ACHED ACCIDENT PHOTO		
			SUSAN	

GTARMC Addenisms Form

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SFG1333A

Date of Accident

23/08/2022

曲

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance _____ AIG Asia Pacific Insurance Pte....

Period of Insurance ______26/07/2022 - 25/07/2023

Requested Date _______26/08/2022 09:50

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: **M400017735**