

Yan (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Thursday, 1 September 2022 10:20 AM
To: assignments
Cc: Operation / Kristine
Subject: RE: ACCIDENT INVOLVING SMD4564M AND SMQ357C ON 19.08.2022 FILTERING ALONG NEW UPPER CHANGI RD TOWARDS BEDOJK SOUTH AVE 3----NOA (Ref: DMPC2200365H/02/CT)

WITHOUT PREJUDICE

Dear LKK

Refer to below email and arrange PRI.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg **Web** www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Operation / Kristine <operation@tlauto.com.sg>
Sent: Thursday, 1 September 2022 9:10 am
To: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Subject: RE: ACCIDENT INVOLVING SMD4564M AND SMQ357C ON 19.08.2022 FILTERING ALONG NEW UPPER CHANGI RD TOWARDS BEDOJK SOUTH AVE 3----NOA (Ref: DMPC2200365H/02/CT)

Without Prejudice,

Dear Crystabelle,

We would like to select Lkk Auto Consultants to conduct PRI.

Thanks & regards,

Kristine Goh



Tong Luck Auto Pte Ltd

160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

From: Crystabelle Tan Gek Peng (ECICS, Claims) [mailto:Crystabelle_Tan@ecics.com.sg]

Sent: Wednesday, 31 August, 2022 5:59 PM

To: operation@tlauto.com.sg

Subject: RE: ACCIDENT INVOLVING SMD4564M AND SMQ357C ON 19.08.2022 FILTERING ALONG NEW UPPER CHANGI RD TOWARDS BEDOJK SOUTH AVE 3----NOA (Ref: DMPC2200365H/02/CT)

WITHOUT PREJUDICE

Dear Kristine

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. Ajax Inspection Services Pte Ltd
2. Appraisals Associates Pte Ltd
3. Infiniti Appraisal Services
4. LKK Auto Consultants

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg **Web** www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Operation / Kristine <operation@tlauto.com.sg>

Sent: Tuesday, 30 August 2022 5:33 pm

To: ECICS Claims <claims@ecics.com.sg>

Subject: RE: ACCIDENT INVOLVING SMD4564M AND SMQ357C ON 19.08.2022 FILTERING ALONG NEW UPPER CHANGI RD TOWARDS BEDOJK SOUTH AVE 3----NOA

Dear All,

We have our client's instruction to notify you the above accident.

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop.

Kindly let us have the surveyor list and arrange for the pre-repair inspection of our client's vehicle at an earlier date

Thanks & regards,

Kristine Goh



Tong Luck Auto Pte Ltd

160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.