




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS3/ASM22008546/Gvy3m4 Date: 06/09/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 1517U	Veh. Inspected	SJE 3819R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04990	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	01/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305046845	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	6 mm
	L/H Front Tyre	185/60 R15	FIRENZA	6 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
	L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
5. General Information				
	Accident Date	17/08/2022	Inspect Date / Time	01/09/2022 (05:20 PM)
	Survey held at	BOOST AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM22008546/Gvy3m4

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.