



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22008549/Kpa3q2 Date: 20/12/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 7934D	Veh. Inspected	SLJ 3502D	
Policy No.	P2459880	Coverage (\$)	0.00	
Claim No.	S2M04A68	Excess (\$)	0.00	
Assign From		Assign Date	01/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHGM6660HP000292	Colour	WHITE	
Odometer	79447 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/08/2022	Inspection Date	06/09/2022	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	