

Our Job Ref No : 305527921  
Date : 01/09/22

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK Fax :  
Attn : Mr Guo Qiang  
Vehicle Reg No. : SHD7238U 26.08.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: **CHINA TAIPING** -- **SMW8216S**
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges
  - Total for Part-By-Part Repair Cost** **\$0.00**
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% **\$3,950.00**  
**Final Lumpsum Repair cost** **\$3,950.00**

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : Ms. Loke YY  
Tel : 62148355  
Fax : 65468156

Signature :  
Name :  
Date :

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

# COMFORT DELGRO ENGINEERING

VEHICLE I SHD7238U

TYPE OF C: TP

CHINA TAIPING

SURVEY B': LKK/ GUO QIANG

305527921

DATE : 01/09/2022

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
REAR BUMPER UNDER SIDE COVER LH	1		\$108.00	✓ CRA
		TOTAL	\$108.00	