

ASS. REC. BY:

REF:

A15/ 22 008574/1K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGT 9303E Yr Regn: 11.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Pro C.C. 1498Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 110429 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CRB7 1100016Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / 8Rim / STD A/Rim orTyre Size: F: 185/65R15

R: _____

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 26/8/22 D.O.I. 29/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ CRB & EN not ready

3/10 61Rm 83430/1

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

) S + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com / HP : 90030857

Date : 29 Aug 2022

QUOTATION -THIRD PARTY CLAIM

ATTN : ALLIANX INSURANCE SINGAPORE

CLAIM : THIRD PARTY CLAIM
VEH. No : SGT 9363 E / HONDA FREED
INSURE : NTUC INCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
1	TAILGATE <i>1245.30</i>	\$ <i>Ry</i> 1,385.60	✓
1	TAILGATE OUTER CHROME <i>264.80</i>	\$ <i>ngcm</i> 480.00	✓
1	TAILGATE CENTER LOGO	\$ <i>na</i> 58.00	✓
1	TAILGATE FREED EMBLEM	\$ <i>na</i> 55.00	✓
1	TAILGATE WEATHERSTRIP	\$ <i>od/di's</i> 168.00	✓
2	TAILGATE LAMPS	\$ <i>sn</i> 1,160.00	X
1	TAILGATE TRIM BOARD <i>391.70</i>	\$ <i>my</i> <i>GA</i> 485.00	X
1	TAILGATE WIPER MOTOR	\$ <i>sn</i> 449.00	X
1	TAILGATE LOCK <i>186.20</i>	\$ <i>nd</i> 480.00	✓
1	TAILGATE LOCK LOWER SENSOR	\$ <i>sn</i> 339.00	X
1	TAILGATE LOCK SWITCH	\$ <i>sn</i> 228.00	X
2	TAILLAMPS	\$ <i>sn</i> 1,256.00	X
2	TAILLAMP PANELS	REPAIR	
2	TAILLAMP LOWER BRACKETS	\$ <i>R</i> 220.00	X
1	REAR BUMPER <i>829</i>	\$ <i>nd/nd</i> 895.00	✓
2	REAR BUMPER SIDE RETAINERS	\$ <i>sn</i> 180.00	X
1	END PANEL	\$ <i>R</i> 580.00	X
1	END PANEL TOP GARNISH <i>115.00</i>	\$ <i>ngcm</i> 332.00	✓
1	END PANEL TOP LATCH	\$ <i>R</i> 62.00	X
	TOTAL PARTS :	\$ 8,812.60	
	LESS 10%	\$ 881.26	
	TOTAL LIST PARTS :	\$ 7,931.34	
	SPECIAL / NETT PARTS		
10	REAR BUMPER CLIPS	\$ <i>na</i> 45.00	✓
1SET	REVERSE CAMERA	\$ <i>sn</i> 500.00	X
1SET	REVERSE SENSORS	\$ <i>shon</i> 300.00	<i>200SN</i>
	TOTAL S/N PARTS :	\$ 845.00	
	TOTAL PARTS PRICE :	\$ 8,776.34	

*Not Authorized
11 Sep @ 3450h*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days

TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com / HP : 90030857

Date : 29 Aug 2022

QUOTATION -THIRD PARTY CLAIM

CLAIM : THIRD PARTY CLAIM
VEH. No : SGT 9363 E / HONDA FREED
INSURE : NTUC INCOME INSURANCE

ATTN : ALLIANX INSURANCE SINGAPORE

LABOUR CHARGES	W/ SHOP RATE	RECOMMEND
Labour charges to repair , replace accident affected, affected area	\$ 800.00	500
Transfer tailgate parts to another tailgate	\$ 140.00	60
To remove refix rear w/screen	\$ 140.00	120
To replace sensors, reverse camera check rear wiring system etc	\$ 150.00	50
To do spray painting on accident affected area inner and outer	\$ 800.00	600
To do computer setting, diagnose delete fault code after repair	\$ ~ 250.00	X
To do sealant seal gap, waterproofing on rear cutting welding area	\$ ~ 150.00	X
To do anti rust	\$ 90.00	30
To remove refix replace garnish, side trims, upholstery etc	\$ 180.00	80
TOTAL LABOUR :	\$ 2,700.00	
GRAND TOTAL PARTS & LABOUR :	\$ 11,476.34	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: