

**Note: This document has not been finalised.**

## **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: ALANO Ana Maria Velarde

Date: 13 Sep 2022

### **Preliminary Advice**

Vehicle No	: SLN1887K	Accident Date	: 22/08/2022
Make	: RENAULT MEGANE	Policy No.	: MP307194
Assignment Date	: 02/09/2022	Excess	: S\$600.00
Date of Inspection	: 12/09/2022	Est. Duration of Repair	: 13
Inspection At	WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD) 249 ALEXANDRA ROAD SINGAPORE 159935		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 30,176.50
Revised Amount	:S\$ 10,715.00
Check Items (Estimated)	:S\$ 3,631.00
Total	:S\$ 14,346.00
Lump Sum Repair	:S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 62,000.00
COE / PARF Rebate	:S\$ 27,398.00
Salvage Value	:S\$
Margin for Repair	:S\$ 34,602.00

## **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.