

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 29.08.2022INSURANCE: NTUC (45)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC3185U

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender RH <i>✓</i>	1		\$ 588.80 <i>✓</i>
	Frt Fender Blue-Drive RH <i>✓</i>	1		\$ 26.60 <i>✓</i>
	DayLight RH <i>X</i>	1		\$ 642.50 <i>✓</i>
	DayLight Grille RH <i>✓</i>	1		\$ 93.45 <i>✓</i>
	Frt Bumper <i>X</i>	1		\$ 481.10
	Frt Bumper Upper Moulding <i>X</i>	1		\$ 368.50
	Frt Bumper Side Bracket RH <i>X</i>	1		\$ 35.00
	Frt Bumper Clips <i>X</i>	10	\$ 2.20	\$ 22.00
	Frt Wheel Cap RH <i>✓</i>	1		\$ 346.40 <i>✓</i>
	HeadLamp RH <i>✓</i>	1		\$ 2,110.30 <i>✓</i>
	Rocker Panel Garnish RH <i>X</i>	1		\$ 290.00
	SUB TOTAL			\$ 5,004.65
	LESS 20%			\$ 1,000.93
	DISCOUNTED TOTAL			\$ 4,003.72
	Labour Charge			
	Panel Beating			\$ 800.00 <i>350</i>
	Spray Painting Charge			\$ 900.00 <i>500</i>
	Check Lightings			\$ 60.00 <i>30</i>
	Tuff Kote			\$ 60.00 <i>40</i>
	Wheel Alignment			\$ 120.00 <i>60</i>
	TOTAL LABOUR			\$ 1,940.00 <i>980</i>
	ESTIMATE TOTAL			\$ 5,943.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3 Days.

4/5

CmR: 4

29/8/22

12 pm

-20%: 2800

LKK Auto Consultant hereby notify
the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) for survey
- Parts prices are subject to market price
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) is subject to final approval

Acknowledged by Repairer:

Signature:

Print: