

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7308B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER COVER | DEFORMED | 459.40 | 459.40 |
| 10 | REAR BUMPER CLIPS | NECESSARY | 22.00 | 22.00 |
| 1 | REAR BUMPER CENTRE MOULDING ASSY | CUT | 451.25 | 451.25 |
| 1 | REAR BUMPER REINFORCEMENT | NOT NECESSARY | 394.80 | - |
| 1 | REAR BUMPER REINFORCEMENT BRACKET LH | NOT NECESSARY | 138.10 | - |
| 1 | REAR BUMPER SIDE BRACKET LH | CUT | 55.80 | 55.80 |
| 1 | REAR BUMPER LOWER CTR MOULDING | BROKEN | 155.00 | 155.00 |
| 1 | REAR BUMPER CENTRE UNDER COVER | NOT NECESSARY | 225.00 | - |
| 1 | REAR BUMPER SIDE UNDER COVER LH | TORN | 108.00 | 108.00 |
| 1 | REAR BUMPER REFLECTOR LAMP LH | CUT | 41.45 | 41.45 |
| | LESS 20% DISCOUNT | | -410.16 | -258.58 |
| | | | 1,640.64 | 1,034.32 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BUMPER RUBBER MAT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR NUMBER PLATE WITH TRIM COVER (SN) | NOT NECESSARY | 55.00 | - |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | NOT NECESSARY | 180.00 | - |
| | | | 285.00 | 50.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. | | 400.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 300.00 | 250.00 |
| | REMOVE / REFIX REVERSE SENSOR. | | 80.00 | 40.00 |
| | | | 780.00 | 640.00 |
| | GRAND TOTAL | | 2,705.64 | 1,724.32 |





Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,350.00 |
|---|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | |

Report Ref No. NS/INC22008585/Gvce2

XING GUO QIANG

Automotive Assessor

M.MATAI, AMSAE-A

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.