

WORLD AUTO PTE LTD

NO.5, KIM CHUAN LANE

S'pore 537070

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-4 Buss. Reg No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

the Repairer of the following:

- To resurvey before/after spray painting
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate : ES190200

Date : 31/08/2022

Vehicle Num. : SMR 4676A

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 18/08/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE / <i>one</i>	1193	1,850.00
2.	1	REAR TAILGATE INNER TRIM BOARD X		230.00
3.	1	REAR TAILGATE LOCK X		155.00
4.	1	REAR TAILGATE INNER HANDGRIP COVER X		30.00
5.	1	REAR TAILGATE SHUTTLE EMBLEM ✓ <i>one</i>		50.00
6.	1	REAR TAILGATE HYBRID EMBLEM ✓		55.00
7.	1	REAR TAILGATE STOPPER RH X <i>one</i>		45.00
8.	1	REAR BUMPER / <i>one</i>	958	1,800.00
9.	1	REAR BUMPER TOW COVER X <i>one</i>		45.00
10.	1	REAR BUMPER SIDE RETAINER RH X <i>one</i>		45.00
11.	1	REAR END PANEL X <i>one</i>		480.00
12.	1	REAR END PANEL TOP GARNISH ✓ <i>one</i>		135.00
13.	1	REAR BOOT WEATHER STRIP ✓ <i>one</i>		128.00
14.	1	REAR BOOT COMPARTMENT BOX X		246.00
15.	1	REAR BOOT COMPARTMENT BOX BACK COVER X <i>one</i>		90.00
16.	1	TAIL LAMP LOWER PANEL RH X		132.00
17.	1SET	REAR WINDSCREEN GLASS MOULDING / <i>one</i>		130.00

List TotalS\$:

3128 5,646.00

20.00% Discount S\$:

1,129.20

2502.4 4,516.80

SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS / <i>one</i>	20	30.00
2.	1SET	REAR BUMPER CLIP / <i>one</i>		30.00
3.	1SET	REAR END PANEL TOP GARNISH CLIPS	20	30.00
4.	1	WINDSCREEN GLASS SEALANT / <i>one</i>	40	80.00
5.	1SET	REVERSE SENSOR / <i>one</i>	200	320.00

Special Nett Total S\$:

490.00

CONTINUE / ...

WORLD AUTO PTE LTD

NO.5, KIM CHUAN LANE

S'pore 537070

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

75 BRAS BASAH ROAD NTUC INCOME CENTRE

189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190200

Date : 31/08/2022

Vehicle Num. : SMR 4676A

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 18/08/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		REMOVE & REFIT REAR WINDSCREEN GLASS	120	180.00
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY INCLUDING DRILL HOLES ON NEW REAR BUMPER FOR INSTALLATION OF NEW SET OF REVERSE SENSORS	40	180.00
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	60	180.00
		REMOVE ACCIDENT DAMAGED PARTS INCLUDING CUT/WELD REAR END PANEL, STRAIGHTEN AND PANEL BEAT REAR AFFECTED AREAS INCLUDING REAR BOOT FLOOR PANEL, REPLACE ABOVE NEW PARTS	400 800	1,200.00
		PUTTY AND SPRAY PAINT REAR ACCIDENT AFFECTED AREAS	700	1,500.00
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK HV HYBRID SYSTEM - photo	7	380.00
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES, REINITIALISE HV HYBRID SYSTEM AND PERFORM WHOLE VEHICLE FUNCTIONALITY CHECK - photo.	250	280.00
		Labour Total S\$:	1920	3,900.00

~~4~~ 5 Days.
part by part.

before paint photo.

E. & O.E.

Total S\$: 8,906.80

=====

Amo Qim - 82880282

4782.4

for WORLD AUTO PTE LTD

2/9/2022