



Co. & GST Regn.
No. 201911943E

KIM SOON LEE ENGINEERING PTE LTD
200 Bedok South Avenue 1
Singapore 469331

TO: **NTUC**
ATTN.: **MOTOR CLAIMS DEPARTMENT**

OUR REF.: **GBJ4767T**
YOUR REF.: **GBD2282U**

DATE: **1 September 2022**
CREATED BY: **CASSANDRA CHUA**
CONTACT NO.: **6741 2222**
VEHICLE NO.: **GBJ4767T**
MAKE & MODEL: **FIAT FLORINO CARGO**
CHASSIS NO.: **ZFA22500006H38154**
ENGINE NO.: **225A20006534809**
YEAR: **2017**
DOA: **30/8/2022**
CLAIM TYPE: **TP**

Please advise the Insurer to notify
any of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• To be subject to confirmation
• The survey is on a "Without Prejudice" basis
• Any modification(s) is allowed
• Any supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE FOR VEHICLE NO.: GBJ4767T

NO.	DESCRIPTION	QTY.	LIST PRICE
PARTS			
1	REAR DOOR LH <i>RM</i>	1	\$ 2,442.50
2	REAR DOOR INNERTRIM LH <i>?</i>	1	\$ 287.50
3	REAR DOOR WEATHERSTRIP <i>?</i>	1	\$ 225.00
4	REAR WINDSCREEN LH <i>SM</i>	1	\$ 380.00
5	TAILLAMP LH <i>CR</i>	1	\$ 535.00
6	"FLORINO" EMBLEM <i>SM</i>	1	\$ 197.50
7	"ECOJET" EMBLEM <i>SM</i>	1	\$ 167.50
8	REAR BUMPER <i>RM</i>	1	\$ 670.00
9	REAR BUMPER CLIP - \$10/PC <i>RM</i>	10	\$ 100.00
10	REAR BUMPER RETAINER LH <i>BT</i>	1	\$ 217.50
11	REAR BUMPER RETAINER RH <i>X NN</i>	1	\$ 217.50
12	REAR BUMPER REINFORCEMENT <i>?</i>	1	\$ 340.00
13	END PANEL CENTRE <i>?</i>	1	\$ 987.50
14	END PANEL LH <i>?</i>	1	\$ 1,390.00
15	REAR FENDER TOP LH <i>X Repair</i>	1	\$ 1,150.00
16	REAR FENDER INNERSHIELD LH <i>X NN</i>	1	\$ 322.50
SUBTOTAL:			\$ 9,630.00
LESS 10%:			\$ 963.00
PARTS TOTAL:			\$ 8,667.00

SPECIAL NETT			
1	"KIM SOON LEE" DECAL <i>SM</i>	1	\$ 200.00 <i>50</i>
2	REAR WINDSCREEN SEALANT <i>SM</i>	1	\$ 100.00 <i>40</i>
3	SPEED LIMIT "70KM/HR" DECAL <i>SM</i>	1	\$ 60.00 <i>10</i>
4	REAR NUMBER PLATE W/ HOLDER <i>SM</i>	1	\$ 90.00 <i>40</i>
5	"WWW.KIMSOONLEE.COM" DECAL <i>SM</i>	1	\$ 200.00 <i>30</i>
6	REVERSE SENSOR <i>X NN</i>	1 SET	\$ 200.00
SPECIAL NETT TOTAL:			\$ 850.00

LABOUR			
	TO REMOVE, REPAIR & INSTALL ALL ACCIDENT AFF. PORTIONS	\$	1,200.00 <i>600</i>
	TO REMOVE & INSTALL REAR WINDSCREEN	\$	200.00 <i>100</i>
	TO REMOVE & INSTALL REVERSE SENSOR	\$	250.00 <i>40</i>
	TO CHECK ENGINE WARNING LIGHT (ABS, ECU, & ETC.)	\$	220.00 <i>20 X NN</i>
	TO CHECK ALL NECESSARY WIRING	\$	160.00 <i>30</i>
	TO CHECK CHASSIS ALIGNMENT	\$	170.00 <i>X</i>
	TO CHECK WHEEL ALIGNMENT	\$	90.00 <i>X SM</i>
	TO CHECK UNDERCARRIAGE	\$	180.00 <i>X</i>
	TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS	\$	1,500.00 <i>500</i>
	TO APPLY ANTI-RUST COATING ON ALL ACCIDENT AFF. PORTIONS	\$	170.00 <i>X NN</i>
LABOUR TOTAL:			\$ 4,140.00
GRAND TOTAL:			\$ 13,657.00

L/S. After repair 5 Days. 6/9/2022
Amo Qian 82880282

BEFORE 7% GST