

lrfm
90097659

05/sep

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-42
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

Date : 15/08/2022
Vehicle : SMP1807U
Make/Model : TOYOTA NOAH HYBRID
ORD : 2019
Chassis : ZWR800386652
ODO :
ACC Date : 13/08/2022

MS First Capital Insurance Ltd

36 Robinson Road, City House, #16-01
Singapore 068877

Estimate

S/N	Qty	Description & Specification	Amount S\$
<u>List Items</u>			
1	1	Front LH Door	\$1,808.30 X R ser
2	1	Front LH Door Inner Lock	\$607.90 X Svc
3	1	Front LH Door Weatherstrip	\$188.60 X NN
4	1	Rear LH Sliding Door	1594 Bv < \$1,966.10 ✓
5	1	Rear LH Sliding Door Inner Board	620 \$685.30 ? / Broken
6	1	Rear LH Sliding Door Inner Lock	(500) \$983.50 X / Faulty
7	1	Rear LH Sliding Door Weatherstrip	\$234.80 ✓ X nn
8	1	Rear LH Fender	Bv < \$1,261.00 X R
9	1	Rear Bumper	\$873.90 X X R
10	1	Rear Bumper Side LH	\$300.60 X R NN
11	1	Rear Bumper Side Retainer LH	\$96.80 * ? X NN
12	1	Rear Bumper Side Bracket LH	\$160.66 X NN
13	1	Rear Bumper Reflector LH	\$125.30 X NN
14	1	Rear LH Wheel Hub With Bearing	450 \$966.80 X / Faulty
15	1	Rear LH Kunckle Arm	\$688.80 X X NN
16	1	Rear LH Shock Absorber	\$441.30 X X NN
17	1	Rear LH Lower Arm	\$996.40 X X NN
Total			\$12,386.06 \$3164
Less 25%			\$3,096.52 \$791
List Total			\$9,289.55 \$2373
<u>S/Nett Items</u>			
1	1 set	Rear bumper clip	\$80.00 X NN
2	1	Rear LH Tyre	\$400.00 ? X NN
3	1	Rear LH Wheel Rim	\$1,219.30 Z R
S/Nett Total			\$1,699.30

<u>Labour</u>		
1	To panel beating, removal and replacing parts	\$2,200.00 600 + 200
2	To putty and respray on accident portion	\$2,200.00 800
3	To check wiring	\$80.00 60 30
4	Remove & Refix Front Windscreen	\$120.00 X
5	Transfer Front Door Mechanism	\$80.00 60 X
6	Remove & Refix Rear Windscreen	\$120.00 X
7	Transfer Rear Sliding Door Mechanism	\$80.00 60
8	Check wiring - Reperated	\$80.00 X
Labour Total		\$4,960.00 1490 + 200
Grand Total		\$15,948.85 4063

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: Trident Auto Service Centre Pte Ltd

L/S 6 days
After Survey Photo
Total = 3250
20% 812