



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



7/9 - Wed @ 9.30am

ESTIMATE

Account Details		Account No.	Customer Details					
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Astee Autolution Pte Ltd 186 Woodlands Industrial Park E5 #04-01L Singapore 757515 Mobile: 98535524					
		Document No. 0						
		Document Date 01/09/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AVE30R	BEXLHQ S1	22/11/2021	SMY0789Y	0	21532	61TP/SMY0789Y/310822	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBH1D2005087774		2AR2666812	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: FIRST CAPITAL ACC DATE: 31.08.2022 T/P VEH: SHB1308B DATE IN: DATE SURVEY: DATE AUTHORIZE:						50 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL AND FIX NEW PARTS						866 1732.00
3	B	BP-RES3 TO SPRAY PAINT ON REAR BUMPER						742 1484.00
4	B	BP-LAB3 TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)						216.50
5	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)						216.50
6	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)						216.50
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
First Capital Insurance Ltd Robinson Road #01 City House Singapore 068877 Motor Claims Dept	S1000005 / ICFIC1	M/S Astee Autolution Pte Ltd 186 Woodlands Industrial Park E5 #04-01L Singapore 757515 Mobile: 98535524
	Document No. 0	
	Document Date 01/09/2022	


Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AVE30R	BEXLHQ S1	22/11/2021	SMY0789Y	0	21532	61TP/SMY0789Y/310822
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
1THBH1D2005087774	2AR2666812	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.				
Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
1	L52159-53955 COVER, RR BUMPER <i>de</i>	1.00	1248.40		1248.40 ✓
2	L52108-53080 EXTENSION SUB-ASSY. <i>sur</i>	1.00	881.20		881.20 ✓
3	S52161-0K040 PIECE, RR BUMPER <i>re</i>	6.00	4.50		27.00 ✓
4	L75392-35220 RETAINER, OUTSIDE <i>re</i>	16.00	4.30		68.80 ✓
5	L52156-53050 SUPPORT, RR BUMPER <i>? xan</i>	1.00	278.20		278.20 ✓
6	L52155-53080 SUPPORT, RR BUMPER <i>? xan</i>	1.00	278.20		278.20 ✓
7	L75895-53010 TAPE, MOULDING, NO.1 <i>re</i>	2.00	55.50		111.00 ✓
8	L52158-53080 SUPPORT, RR BUMPER <i>? xan</i>	1.00	124.00		124.00 ✓
9	L52157-53080 SUPPORT, RR BUMPER <i>? xan</i>	1.00	124.00		124.00 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Astee Autolution Pte Ltd 186 Woodlands Industrial Park E5 #04-01L Singapore 757515 Mobile: 98535524			
			Document No.					
			0					
			Document Date					
			01/09/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AVE30R	BEXLHQ S1	22/11/2021	SMY0789Y	0	21532	61TP/SMY0789Y/310822	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBH1D2005087774		2AR2666812	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
18	0	L52615-53160	ABSORBER, RR BUMPER ? cra /			1.00	138.10	138.10
19	1	L52023-53091	REINFORCEMENT ? xan			1.00	966.10	966.10
20	2	L89341-33220 A3	SENSOR, ULTRASONIC, ? xan			4.00	491.40	1965.60
21	3	L81920-53060	REFLECTOR ASSY, ? xan			1.00	52.70	52.70
22	4	L81910-53060	REFLECTOR ASSY, ? xan			1.00	52.70	52.70
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Passer</i> <i>4p 90010068</i> <i>3 days</i> <i>P/P</i> <i>07/09/22 P 0930</i> <i>Resy before paint</i>								
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							10,281.50	
			Please acknowledge receipt of vehicle		Parts		GST 7.00%	
					Labour		719.71	
					Sublet		Less	
					Lubrication/Fluid		0.00	
					Others		Amount Due	
					6,316.00		11,001.21	
					3,965.50			
					0.00			
					0.00			
					0.00			