

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA4624Z

Date: 30/08/2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR DOOR LH <i>BT</i>			\$ 2,147.90	✓
1	REAR FENDER LH <i>X</i>			\$ 1,768.30	
1	REAR WHEEL HUB CAP LH <i>Cut</i>			\$ 346.40	✓
1	FRT DOOR LH <i>BT</i>			\$ 1,797.20	✓
1	REAR BUMPER COVER <i>Cut</i>			\$ 459.40	✓
10	REAR BUMPER CLIPS <i>mbc</i>			\$ 22.00	✓
SUB TOTAL				\$ 6,541.20	
LESS 20%				\$ 1,308.24	
DISCOUNTED TOTAL				\$ 5,232.96	
REAR BUMPER RUBBER MAT <i>/</i>				\$ 50.00	✓
FRT DOOR COMFORT LOGO STICKER LH <i>/</i>				\$ 75.00	✓
RR DOOR COMFORT DELGRO LOGO STICKER LH <i>/</i>				\$ 80.00	✓
REAR FENDER "PETROL ONLY" STICKER <i>X</i>				\$ 15.00	
RENEW ADVERTISEMENT LOGO <i>X</i>				\$ 550.00	
NETT				\$ 770.00	
Labour Charge					
PANEL BEATING				\$ 1,100.00	
SPRAY PAINTING CHARGE				\$ 1,250.00	
TUFF KOTE				\$ 60.00	
TRANSFER OF DOOR				\$ 240.00	
TOTAL LABOUR				\$ 2,650.00	
ESTIMATE TOTAL				\$ 8,652.96	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days.

45

Gua Qian

30/8/22

3pm

-20%: 4650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Suppliers to resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date