

COMFORTDELGRO ENGINEERING PTE LID

REPAIR ESTIMATE*

VEHICLE NO SHA5953S

30.08.2022

MAKE REG 31.08.2022

MODEL PRIUS G4

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER ASSY <i>✓ vze</i>			\$586.18 ✓
10	FRONT BUMPER CLIP <i>✓ mcl</i>			\$2.20 ✓
1	FRONT UNDER COVER <i>✓ le</i>			\$180.80 ✓
1	FRONT BUMPER BRACKET LH <i>✓ cut</i>			\$77.00 ✓
1	FRONT RADIATOR GRILLE EMBLEM <i>✓ mcl</i>			\$88.00 ✓
1	FRONT BUMPER HOLE LH <i>X repair</i>			\$28.38 ✓
1	FRONT HEADLAMP ASSY LH <i>✓ crA</i>			\$2,735.28 ✓
1	FRONT FOG LAMP LH <i>2. NN</i>			\$920.00
1	FRONT FENDER SHIELD LH <i>X</i>			\$198.50
1	FRONT WHHEEL COVER LH <i>X</i>			\$189.60
1	FRONT FENDER EMBLEM LH <i>X</i>			\$86.20
	SUB TOTAL			\$5,092.14
	25.00%			\$1,273.03
	DISCOUNTED TOTAL			\$3,819.10
1	FRONT FENDER ADVERTISEMENT <i>X NN</i>			\$100.00
				\$100.00
	Labour Charge			
	Panel Beating		<i>2450</i>	\$700.00
	Spray Painting Charge		<i>250</i>	\$600.00
	Reset front wheel alignment		<i>NPX</i>	\$60.00
	Check Wiring & Lighting		<i>30</i>	\$60.00
	TOTAL LABOUR			\$1,420.00
	ESTIMATE TOTAL			\$5,339.10
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Days
4/5
Guey
21/8/22
2pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification
- Supplemental cost must be received and is subject to approval by the insurance company

Acknowledged by:

Signature

Date

-20%: 2700