

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK-

DATE: 23.08.22

MODEL: Hyundai Ioniq

INSURANCE: CHINA TAIPING (L/S)

VEHICLE NO.: SHC1389L

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender RH	1		\$ 588.80
	Frt Fender Blue-Drive RH	1		\$ 26.60
	DayLight RH	1		\$ 642.50
	DayLight Grille RH	1		\$ 93.45
	Frt Bumper	1		\$ 481.10
	Frt Bumper Upper Moulding	1		\$ 368.50
	Frt Bumper Side Bracket RH	1		\$ 35.00
	Frt Bumper Clips	10	\$ 2.20	\$ 22.00
	SUB TOTAL		529.70	\$ 2,257.95
	LESS 20% DISCOUNTED TOTAL		423.76	\$ 451.59
				\$ 1,806.36
	Frt Fender Adv. Sticker RH	1	100	\$ 100.00
	Labour Charge			
	Panel Beating		850	\$ 800.00
	Spray Painting Charge			\$ 600.00
	Check Lightings		1373.76	\$ 60.00
	Tuff Kote			\$ 60.00
	TOTAL LABOUR		4591.10	\$ 1,520.00
	ESTIMATE TOTAL		2 days	\$ 3,426.36

Ry
ner
xnn
xnn
dl-
xnn
Rnn
ner

ent -
NETT

350
500
xnn
xnn

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
in 23/8/22 C430 p
15 hrs after repair
Tanpin Chhantawon
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: