

ASS. REC. BY: Marcus

REF:

CCG/CT122008656/4023

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

27A 12746

Veh No:

SMC 65402

Yr Regn:

16/07/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/ALS

Make:

Hyundai Elantra OPC

c.c

1591

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

56721

T/Radio: Insured / Std / NI / NA

Eng/No:

KMHD841CMJU 705215

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/9/22

D.O.I.

5/9/22

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reg 9k.

14/9/22 4/5 @ 5000 inland AH head

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __S + RS, __SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)

TAI AUTOMOTIVE PTE. LTD.

100, KI BUKIT AVE 6 #02-47
 BAY SINGAPORE 417883
 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
SMP311P

Asst

Not Available

5/9/22

1/5 \$5000

5 days

ESTIMATE

VEHICLE NO : SMC6540Z
 MAKE/MODEL : HYUNDAI ELANTRA
 ACC DATE : 03.09.2022

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
	<u>LIST PRICE</u>		
1	1 REAR BOOT LID	1,783.00	1,783.00
2	1 REAR BOOT LOGO	42.60	42.60
3	1 REAR BOOT EMBLEM "ELANTRA"	58.80	58.80
4	2 REAR BOOT LAMPS RH/LH	441.50	883.00
5	1 REAR BOOT INNER LOCK	210.60	210.60
6	1 REAR BOOT INNER TRIM	241.60	241.60
7	10 REAR BOOT INNER TRIM CLIPS	5.50	55.00
8	1 REAR BOOT W/STRIP	161.90	161.90
9	2 REAR BOOT HINGES - RH/LH	110.50	221.00
10	2 REAR BOOT STOPPER	10.50	21.00
11	1 REAR BUMPER	571.60	571.60
12	1 REAR BUMPER DIFUSSER	281.90	281.90
13	2 REAR BUMPER REFLECTOR RH/LH	89.90	179.80
14	1 REAR BUMPER REINFORCEMENT	431.60	431.60
15	2 REAR BUMPER SIDE RETAINERS - RH/LH	65.50	131.00
16	1 REAR END PANEL	520.60	520.60
17	1 REAR END PANEL GARNISH	161.20	161.20
18	1 REAR EXHAUST SILENCER	762.80	762.80
19	1 REAR FLOOR BOARD	415.90	415.90
20	2 REAR FENDER INNER TRIMS - RH/LH	430.60	861.20
21	2 REAR TAILLAMPS - RH/LH	551.20	1,102.40
22	2 REAR TAILLAMP PANELS - RH/LH	195.00	390.00
23	1 REAR SMART KEYLESS ANTENNA	191.60	191.60
			9,680.10
		LESS 20%	1,936.02
			7,744.08

5457.2
 202
 4365.76
 305
 1690
 6360.76
 202
 5088

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>SPECIAL NETTS ITEM</u>			
1	1 (SET) REAR BUMPER CLIP <i>new</i>	45.00	45.00 ✓
2	1 (SET) REAR REVERSE SENSOR <i>shorted</i>	280.00	280.00 200
3	1 REAR WEEKEND PLATE SEAL <i>new</i>	30.00	30.00 20
4	1 (SET) REAR NUMBER PLATE WITH HOLDER <i>new</i>	60.00	60.00 40
			415.00
<u>LABOUR CHARGES :</u>			
1	TO CHECK REAR ELECTRICAL WIRING		50.00 20
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR		120.00 60
3	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS		80.00 50
4	TO RESPRAY UNDERCOATING		100.00 60
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,080.00 900
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,050.00 600
TOTAL:			2,480.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 10,639.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: