

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

L74436236

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 1st

16/9/22 2/54 9200 informed Angie.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __ S + RS, __ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

5-Sep-22

Our ref : TP/5160/22

Sng Lihui

Not Authorized
LH
4/5 # 9200
6/9/22
The ght. Affs.
Repair
10 days.

RE : estimate cost for vehicle no : SLL 7181J

1 pc	frt rh fender	Body	\$	781.20	—
1 pc	frt rh fender VVT-I emblem	new		54.00	—
1 pc	frt rh fender inner shield	Torn		200.90	—
10 pcs	frt rh fender inner shield clips	new		50.00	—
1 pc	frt rh fender inner garnish	Torn		108.70	—
1 pc	frt rh rim	new		2,190.40	6005/20
1 pc	frt rh shock sorber	11		398.10	X
1 pc	frt rh knuckle arm	11		521.50	X
1 pc	frt rh knuckle bearing	Daye		120.00	✓
1 pc	frt rh lower arm	11		608.10	X
1 pc	frt rh door	Dis		1,100.00	—
2 pcs	frt rh door hinges	11		162.40	—
1 pc	frt rh door catch	11		152.00	—
1 pc	frt rh door lock	11		576.50	X
1 pc	frt rh door rubber	new		172.40	—
1 pc	frt rh door sticker	new		66.10	—
1 pc	frt rh door trimboard	De/Torn		1,036.00	—
1 pc	frt rh door speaker	11		309.90	X
1 pc	frt rh door outer chrome	11		149.30	X
1 pc	frt rh door regulator gear	Body		304.70	—
1 pc	frt rh door regulator motor	11		996.60	—
1 pc	rear rh door	Body	600-10	1,079.60	—
1 pc	rear rh door sticker	new		61.70	—
1 pc	rear rh door outer chrome	11		149.30	X
1 pc	rear rh door rubber	new		174.60	—
1 pc	rear rh door trimboard	De/Torn		805.10	—
2 pcs	rear rh door hinges	11		170.00	X
1 pc	rear rh fender	Body		986.80	—
1 pc	rear bumper	11		486.50	X
1 pc	rear bumper rh mudflap	CU		52.80	—
1 pc	rear bumper rh retainer	11		110.50	X
1 pc	rh door pillar	DD/Body		367.80	—
1 pc	rh rocker panel	Body		568.20	—
1 pc	rear rh rim	CU		2,190.40	6005/20
				17,262.10	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SLL 7181J

Bal brought forward:	\$	17,262.10
	less 25%	4,315.53
		<u>12,946.58</u>

1 pc	frt rh tyre	SVL	400.00	snett X
1 pc	rear rh tyre	cu7 LP200	400.00	60% 120 S/N
1 pc	rear w/screen gum	net	50.00	40 S/N
Panel beating.			1,500.00	1400
Spray painting.			1,800.00	1400
Transfer 2 doors parts.			160.00	100
Alignment.			80.00	✓
Undercarriage.			400.00	150
Remove & refit rear w/screen.			120.00	✓
Upholstery.			120.00	80
Rust proofing.			80.00	✓
			<u>18,056.58</u>	
			Plus 7% GST	
			1,263.96	
			<u>19,320.54</u>	

SD : Nineteen thousand three hundred twenty & cents fifty-four only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-9025.1
252
6753.82
1360
3410
11823.82
222
9219.