

- LKK Auto Consultants hereby certify the Repairer of the following:
- To resurvey before/after repair/painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

not allowed
6/9/22

1/s # 3600
Telephone: 9299 6636
Date: 05-Sep-22
H. Lys.

Estimated repair cost of GRF 344 B Toyota Dyna

Qty	Description		Amt S(\$)
<u>List Items</u>			
1	Centre black garnish	1u	\$ 285.60 X
1	Front side black garnish -RH	SCA	\$ 199.75 X
1	Front headlamp -RH	CNG	\$ 1,080.50 X
1	Front panel	R	\$ 1,066.50 X
1	Front panel "DYNA" emblem	ner	\$ 58.50 X
1	Front corner panel -RH	DD	\$ 276.50 X
1	Front grille	R	\$ 648.69 X
1	Front grille clip set	11	\$ 68.50 X
1	Front grille logo	11	\$ 75.00 X
1	Front bumper	wegub	\$ 682.80 X
1	Front bumper bracket	11	\$ 158.00 X
1	Front door -RH	Body DD	\$ 1,568.60 X
1	Front door checker	11	\$ 131.75 X
2	Front door hinges	11	\$ 157.00 X
1	Front door lock	11	\$ 375.85 X
1	Front door lettering	ner	\$ 45.00 X
1	Front door rubber	Torn	\$ 190.05 X
1	Front door side mirror	11	\$ 241.62 X
1	Front door pillar	R	\$ 489.50 X
			\$ 7,799.71
		Less 25%	\$ 1,949.93
			\$ 5,849.78

Special Nett Items

1	Front door company sticker	ner	\$ 300.00 180
			\$ 300.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$ 80.00 20
2	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.		\$ 180.00 60
3	To apply undercoating.		\$ 150.00 50
4	Panel beating.		\$ 1,400.00 500
5	To re-spray painting on the affected areas.		\$ 1,200.00 800
			\$ 3,010.00

Grand Total : \$ 9,159.78

P-389395
252
292046
453046
3624.