



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SNC 745 C

Parts	(a) Cost / List Price Items	\$	11,673.00
	Plus/Less 10%	\$	1,167.30
	Total of Cost / List	\$	10,505.70
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	730.00
Total Parts Cost		\$	11,235.70
Labour		\$	2,270.00
Total		\$	13,505.70

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to their approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Date: 20/9/22

28.4/13

2157



ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SNC 745 C
Make & Model : KIA CERATO
Chassis No : KNAF1416MN5115574

Submit By : Carmen Lim

Year Manufacture : 2021 Sep

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>773</i>	<i>Buy</i> 1	\$773.00		✓
2	Front bumper lower garnish	<i>PU</i> 1	\$468.00		X
3	Front bumper clip	<i>Vec</i> 10	\$35.00		✓
4	Front bumper side retainer LH	<i>DI</i> 1	\$36.00		✓
5	Headlamp LH <i>2785</i>	<i>GT</i> 1	\$2,885.00		✓
6	Fog lamp LH	<i>SL</i> 1	\$662.00		X
7	Fog lamp cover LH	<i>mgcm</i> 1	\$115.00		X
8	LH front fender	<i>BU</i> 1	\$653.00		✓
9	LH front fender undershield	<i>PU</i> 1	\$115.00		X
10	LH front fender undershield clip	<i>an</i> 10	\$35.00		X
11	LH front lower arm	<i>PU</i> 1	\$448.00		X
12	LH front shock absorber	<i>SL</i> 1	\$428.00		X
13	LH front shock absorber top mouting	<i>SL</i> 1	\$65.00		X
14	LH front knuckle arm	<i>SL</i> 1	\$405.00		X
15	LH front knuckle bearing	<i>an</i> 1	\$554.00		X
16	LH front wheel hub	<i>an</i> 1			
17	LH front tie rod	<i>SL</i> 1	\$115.00		X
18	LH front tie rod end	<i>SL</i> 1	\$98.00		X
19	LH front drive shaft	<i>SL</i> 1	\$898.00		X
20	LH front rim	<i>SL</i> 1	\$380.00	S.N	✓
21	LH front tyre	<i>SL</i> 1	\$350.00	S.N	X
22	Headlamp LH	<i>Replaced</i> 1	\$2,885.00		X
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

S/S
Yeh
Mok
Cha
S/N



ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Supplementary

Share Parts

Vehicle No. : **SNC 745 C**
Make & Model : **KIA CERATO**
Chassis No. : **KNAF1416MN5115574**

Submit By : **JENNY**
Year Manufacture : **2021 Sep**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp Garnish LH <i>CM</i>	1	\$75.00		✓
2	Front upper grille side garnish LH <i>Ad</i>	1	\$53.00		✓
3	Front bumper inner air duct <i>CM</i>	1	\$47.00		✓
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

DK