



# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SKQ 7463 G  
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727  
 ATTN: Motor Claim Department

Estimate No: ES2290909/WS  
 Date: 06 Sep 2022  
 Policy No: 5105987385-03  
 Veh Reg No: SKQ7463G  
 Make/Model: MAZDA MAZDA 3 4-DOOR SEDAN 1.5L SP.6EAT  
 Chassis No: JM6BM42A8F0139746  
 Engine No: P520225057  
 Reg. Date: 23/12/2014

WS Ref: TP/AIG  
 Claim Type: Third Party  
 Accident Date: 05/09/2022  
 TP Veh Reg No: GBB9592P

*Not Notarised  
 1/1 Sep @  
 Resurvey After Pain  
 & delay*

## Estimate Repair Cost to Vehicle No :SKQ7463G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>List Price</b>				
1 FRONT BUMPER	897.00	1 PC	CPS 897.00	—
2 FRONT BUMPER RH RETAINER	35.00	1 PC	CMS 35.00	—
3 FRONT BUMPER CLIPS	3.50	6 PCS	MC 21.00	—
4 FRONT BUMPER RH FOG LAMP	368.00	1 PC	GA 368.00	7
5 FRT BUMPER RH FOG LAMP GARNISH	63.00	1 PC	GA 63.00	—
6 FRONT BUMPER RH FOG LAMP CHROME GARNISH	113.00	1 PC	GA 113.00	—
7 RH HEADLAMP WASHER PUMP	254.00	1 PC	254.00	7
8 RH HEADLAMP WASHER PUMP COVER	89.00	1 PC	MIS 89.00	—
9 FRONT GRILLE RH INNER RETAINER	25.00	1 PC	25.00	7
10 FRONT GRILLE RH INNER BRACKET	37.00	1 PC	37.00	7
11 RH HEADLAMP	2,354.00	1 PC	Bu 2,354.00	—
12 FRONT RH FENDER	349.00	1 PC	R 349.00	—
13 FRONT RH FENDER LINER	135.00	1 PC	MIS/CMS 135.00	—
14 FRONT RH FENDER LINER CLIPS	3.50	6 PCS	MC 21.00	—
			4,761.00	
		Less 20%	952.20	3,808.80
<b>Labour</b>				
15 REMOVE DAMAGED PARTS & ATTACHMENTS,PANEL BEAT & REPAIR FRT SUPPORT PANEL,RH INNER SIDE PANEL,BONNET	750.00	1 LA	750.00	500
16 PAINTING - FRT BUMPER,FRT RH FENDER,BONNET,BUMPER TOP PAD & FRT RH INNER PANEL	800.00	1 LA	800.00	600
17 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,580.00	1,580.00

Total SS 5,388.80  
 Add GST @ 7% 377.22  
**Total Amount Payable SS 5,766.02**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	05/09/2022 14:48 (SGT)
Reported by	Both
Date of Accident	05/09/2022 12:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	1032 Yishun Industrial Park A
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ7463G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	GOH CHIANG LONG
NRIC No	S7508722E
Email Address	lawrence@fpc.com.sg
Mobile Phone No	(Phone) +65-94550182
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mazda
Model	3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5105987385-03

### DRIVER


Name of Driver	GOH CHIANG LONG
NRIC No	S7508722E
Date Of Birth	31/03/1975
Occupation	Indoor

Describe Circumstance of the Accident

I was being informed by my friend that my vehicle was being hit by vehicle B while my vehicle was parked. I went ahead and check my vehicle condition, there was damage found on front bumper, mostly on the right side, and there was a note written by vehicle B's company stated that their driver accidentally collided into my parked vehicle.

Declaration

I've declare the foregoing particulars are true in every respect.

  
Date: 05/10/2021

Witness Name: \_\_\_\_\_  
Date: \_\_\_\_\_

 Wak Ching (Chong)  
Name of NAICID user