

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 21 October 2022 3:57 PM
To: ENG HUEY NI
Cc: MT_Claim_SG; Admin A
Subject: [SEEK MANDATE] - Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022 *** LKK REF: CC4/LPC22008708/Rpa3 // Lonpac ref: 22/22/22/VC05/026204
Attachments: LKK Survey Report & Photos.pdf; TP LOD & Docs.pdf

Your ref: **22/22/22/VC05/026204**
Our ref : CC4/LPC22008708/Rpa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING XD6994L(LONPAC) AND PC6447A(TP) ON 27/08/2022

We refer to the above matter.

The accident occurred when our driver reversed out from parking lot and collided with third party. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer **"LEXBUILD AUTO & TRADING PTE LTD"** at **\$10,770.50(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 24,931.00	\$ 9,148.50 (\$8,550.00 + 7%GST)
2. Loss of Use (9days x \$350.00)	\$ 3,150.00	\$ 1,620.00 (9days x \$180.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 28,083.00	<u>\$ 10,770.50</u>

Surveyor recommended 7days for repair + 1PRS + 1Sunday = 9days.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 11/10/2022 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Sent: Monday, 12 September 2022 5:58 PM

To: ENG HUEY NI <hneng@lonpac.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022 *** LKK REF: CC4/LPC22008708/Rpa3 // Lonpac ref: 22/22/22/VC05/026204

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ENG HUEY NI <hneng@lonpac.com>

Sent: Tuesday, 6 September 2022 9:07 AM

To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022 *** LKK REF: CC4/LPC22008708/Rpa3 // Lonpac ref: 22/22/22/VC05/026204

Lonpac External - Confidential

Hi Mei Kwan,

As requested, please see the attached OI GIA.

Thank you.


Best Regards

Eng Huey Ni

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04 The Concourse, Singapore 199555

DID: 6279 9244 | Fax: (65) 6296 2706



We are committed to acting professionally, fairly and with integrity. We do not condone bribery, fraud or corrupt practices.

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Sent: Monday, 5 September 2022 6:40 pm

To: ENG HUEY NI <hneng@lonpac.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022 *** LKK REF: CC4/LPC22008708/Rpa3

Dear Huey Ni,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Hsiao Tong.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Sent: Monday, 5 September 2022 3:17 PM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>

Subject: RE: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022

Dear Gerald,

Thank you for the assignment.

Repairer arrange on 6.9.22.

Best Regards,

Yan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 5 September 2022 2:26 PM
To: 'assignments' <assignments@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022

Lonpac External - General

Our Ref : 22/22/22/VC05/026204 (Huey Ni's case)

Dear Yan,

FYNA.

Best Regards

Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/06 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

We are committed to acting professionally, fairly and with integrity. We do not condone bribery, fraud or corrupt practices.

From:
From: Alvin Tey <alvin.lexbuildauto@gmail.com>
Sent: Monday, 5 September 2022 1:56 pm
To: Customer SG <customer_sg@lonpac.com>
Subject: Request Pre-Repair Inspection for Accident Involving PC6447A & XD6994L on 27.08.2022

Dear Officer-In-Charges,

Please refer to the above mentioned.

Thank You.

Regards,
Alvin Tey
Lexbuild Auto & Trading Pte Ltd
Address: No 74, Sungei Kadut Street 1, Singapore 729374.
Tel : 6858 6888 (109) / 6362 3393

We are committed to acting professionally, fairly and with integrity. We do not condone bribery, fraud or corrupt practices.