

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0765/2022/EQ  
**DATE** : 2-Sep-22  
**WIP** : 40176

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 05/09/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

*Hi Adrian*

*11 days exclude weekend*

*9 Dec 22 - Johnny Boo*

**OWNER'S NAME** : MR TOH TECK KIONG  
**ADDRESS** : BLK 10 CHAI CHEE ROAD  
#02-09  
SINGAPORE 467010  
**TELEPHONE** : HP +65 91771643  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220030428  
**VEHICLE NO** : **SLZ 173 E**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 25/3/2022  
**ENGINE NO** : DEM 035964  
**CHASSIS NO** : WAUZZZF58NA010536  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 1-Sep-22  
**PLACE OF ACCIDENT** : PIE (CHANGI) ENTERING KPE (TPE),  
IN THE START OF THE TUNNEL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E**

| S/N                         | NATURE OF JOBS                                                                                                                                   |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00               | \$        | <b>480.00</b>                 |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                           | S/N \$ | 800.00               | \$        | <b>250.00</b>                 |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.         | S/N \$ | 1,600.00             | \$        | <b>1,600.00</b>               |
| 4                           | TO CARRY OUT VACUUM AND REGAS FOR R1234.                                                                                                         | S/N \$ | 1,200.00             | \$        | <b>1,200.00</b>               |
| 5                           | TO REMOVE AND REINSTALL BOTH DOOR PANEL TRIM.<br>TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY<br>TO FACILITATE RESPRAY OF BOTH FRONT DOOR.      | S/N \$ | 560.00               | \$        | <b>280.00</b>                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | :      | <b>\$ 4,640.00</b>   | <b>\$</b> | <b>3,810.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                                   |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
|                             |                                                                                                                                                                                                                                                                  | C/F    |                      | \$ 3,810.00                   |
| 6                           | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 7,200.00             | \$ 2,500.00                   |
| 7                           | TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR.                                                                                                                                                           | \$     | 7,500.00             | \$ 2,750.00                   |
| 8                           | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.                                                                                                                                                                                                                          | S/N \$ | 384.00               | \$ 384.00                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                                  | :      | <b>\$ 19,724.00</b>  | <b>\$ 9,444.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E**

| S/N                          | PARTS DESCRIPTION                              | QTY | DAMAGED PARTS & PRICES |                 |                    |
|------------------------------|------------------------------------------------|-----|------------------------|-----------------|--------------------|
|                              |                                                |     | S/NETT                 |                 | REMARKS            |
| 1                            | FRONT BUMPER                                   | 1   | \$                     | 2,493.00        | \$ 1,994.40        |
| 2                            | FRONT BUMPER SECURING STRIP                    | 2   | \$                     | 79.00           | \$ 63.20           |
| 3                            | FRONT BUMPER GRILLE - CENTER                   | 1   | \$                     | 219.00          |                    |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE    | 1   | \$                     | 293.00          | \$ 234.00          |
| 5                            | FRONT BUMPER SPOILER                           | 1   | \$                     | 599.00          |                    |
| 6                            | RADIATOR AIR GUIDE - LH / RH                   | 2   | \$                     | 144.00          |                    |
| 7                            | FRONT BUMPER CLOSING ELEMENT                   | 1   | \$                     | 293.00          |                    |
| 8                            | RADIATOR AIR GUIDE GRILLE - LH / RH            | 2   | \$                     | 302.00          |                    |
| 9                            | RADIATOR AIR GUIDE GRILLE OUTER TRIM - LH / RH | 2   | \$                     | 108.00          |                    |
| 10                           | RADIATOR GRILLE TRIM - CENTER                  | 1   | \$                     | 127.00          |                    |
| 11                           | RADIATOR GRILLE                                | 1   | \$                     | 1,881.00        | \$ 1,504.80        |
| 12                           | RADIATOR GRILLE COVER CAP                      | 1   | \$                     | 141.00          | \$ 112.40          |
| 13                           | RADAIOR GRILLE BRACKET                         | 1   | \$                     | 19.00           | \$ 14.64           |
| 14                           | FRONT CAMERA                                   | 1   | \$                     | 1,264.00        |                    |
| 15                           | FRONT BUMPER FOAM FILLER PIECE                 | 1   | \$                     | 163.00          | \$ 130.40          |
| 16                           | FRONT BUMPER CARRIER                           | 1   | \$                     | 899.00          | \$ 719.20          |
| 17                           | FRONT BUMPER BRACKET - LH / RH                 | 2   | \$                     | 508.00          | \$ 406.40          |
| 18                           | FRONT BUMPER GUIDE SECTION - LH / RH           | 2   | \$                     | 82.00           | \$ 32.24           |
| 19                           | FRONT BUMPER TOP COVER                         | 1   | \$                     | 143.00          | \$ 114.00          |
| 20                           | CAUTION SIGN STICKER                           | 1   | \$                     | 16.00           | \$ 12.40           |
| <b>SUB TOTAL SPARE PARTS</b> |                                                | :   | \$                     | <b>9,773.00</b> | \$ <b>5,338.08</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E**

|                              |                                            |     | DAMAGED PARTS & PRICES |                    |
|------------------------------|--------------------------------------------|-----|------------------------|--------------------|
| S/N                          | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS            |
|                              |                                            | c/f |                        | \$ 5,338.08        |
| 21                           | AIR CONDITIONER STICKER                    | 1   | \$ 9.00                | \$ 6.64            |
| 22                           | LOCK CARRIER                               | 1   | \$ 154.00              | \$ 122.80          |
| 23                           | FRONT BUMPER SUPPORT - LH / RH             | 2   | \$ 64.00               | \$ 51.04           |
| 24                           | FRONT PARKING AID SENSOR - INNER / OUTER   | 4   | \$ 1,062.00            |                    |
| 25                           | FRONT PARKING AID SEAL RING                | 4   | \$ 10.00               |                    |
| 26                           | FRONT BUMPER WIRING SET                    | 1   | \$ 449.00              |                    |
| 27                           | HORN HIGH TONE - LH                        | 1   | \$ 134.00              |                    |
| 28                           | HORN LOW TONE - RH                         | 1   | \$ 139.00              |                    |
| 29                           | HORN BRACKET - LH / RH                     | 2   | \$ 66.00               |                    |
| 30                           | FRONT FENDER - LH / RH                     | 2   | \$ 2,378.00            |                    |
| 31                           | FRONT FENDER ATTACHMENT PARTS              | 1   | \$ 55.00               |                    |
| 32                           | FRONT FENDER CLOSING ELEMENT - LH / RH     | 2   | \$ 166.00              |                    |
| 33                           | FRONT FENDER BRACKET - LH / RH             | 2   | \$ 82.00               |                    |
| 34                           | FRONT FENDER RIVET                         | 11  | \$ 42.00               |                    |
| 35                           | FRONT FENDER BRACE - LH / RH               | 2   | \$ 264.00              |                    |
| 36                           | FRONT WHEEL HOUSING LINER - LH / RH        | 2   | \$ 598.00              |                    |
| 37                           | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | 1   | \$ 176.00              |                    |
| 38                           | FRONT WHEEL SPOILER - LH / RH              | 2   | \$ 164.00              |                    |
| 39                           | BONNET                                     | 1   | \$ 3,491.00            | \$ 2,792.80        |
| 40                           | BONNET ATTACHMENT PARTS                    | 1   | \$ 128.00              |                    |
| <b>SUB TOTAL SPARE PARTS</b> |                                            | :   | <b>\$ 9,631.00</b>     | <b>\$ 8,311.36</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E**

|                              |                                             |            | DAMAGED PARTS & PRICES |         |           |
|------------------------------|---------------------------------------------|------------|------------------------|---------|-----------|
| S/N                          | PARTS DESCRIPTION                           | QTY        | S/NETT                 | REMARKS |           |
|                              |                                             | <i>c/f</i> |                        | \$      | 8,311.36  |
| 41                           | BONNET HINGE - LH / RH                      | 2          | \$ 932.00              |         |           |
| 42                           | BONNET IMPACT PROTECTION - CENTER / LH / RH | 3          | \$ 93.00               | \$      | 73.20     |
| 43                           | BONNET SOUND ABSORBER                       | 1          | \$ 382.00              | \$      | 305.60    |
| 44                           | BONNET BOWDEN CABLE - CENTER                | 1          | \$ 64.00               | \$      | 50.56     |
| 45                           | BONNET RELEASE LEVER                        | 1          | \$ 15.00               |         |           |
| 46                           | BONNET BOWDEN CABLE - CENTER                | 1          | \$ 64.00               | \$      | 50.56     |
| 47                           | BONNET BOWDEN CABLE COVER                   | 1          | \$ 11.00               |         |           |
| 48                           | BONNET STRIKER - LH / RH                    | 2          | \$ 112.00              | \$      | 89.12     |
| 49                           | BONNET LOCK                                 | 2          | \$ 455.00              | \$      | 364.00    |
| 50                           | FRONT FENDER TOP LEDGE COVER - LH / RH      | 2          | \$ 80.00               |         |           |
| 51                           | FRONT FENDER INNER LEDGE COVER - LH / RH    | 2          | \$ 98.00               | \$      | 77.28     |
| 52                           | HEADLIGHT - LH / RH                         | 2          | \$ 16,344.00           | \$      | 6,537.60  |
| 53                           | HEADLIGHT HOSE                              | 1          | \$ 42.00               |         |           |
| 54                           | HEADLIGHT COMPENSATING PIECE                | 2          | \$ 90.00               | \$      | 71.04     |
| 55                           | HEADLIGHT COMPENSATING PIECE                | 1          | \$ 47.00               |         |           |
| 56                           | LIFT CYLINDER BRACKET - RH                  | 1          | \$ 17.00               |         |           |
| 57                           | LIFT CYLINDER - LH / RH                     | 2          | \$ 434.00              |         |           |
| 58                           | LIFT CYLINDER CORRUGATED PIPE               | 1          | \$ 107.00              |         |           |
| 59                           | LOCK CARRIER                                | 1          | \$ 1,478.00            | \$      | 901.60    |
| 60                           | COOLANT REGULATOR SUPPORT - LH / RH         | 2          | \$ 85.00               |         |           |
| <b>SUB TOTAL SPARE PARTS</b> |                                             | :          | \$ 20,950.00           | \$      | 16,831.92 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E**

|                              |                                    |      | DAMAGED PARTS & PRICES |              |
|------------------------------|------------------------------------|------|------------------------|--------------|
| S/N                          | PARTS DESCRIPTION                  | QTY  | S/NETT                 | REMARKS      |
|                              |                                    | c/f  | \$                     | 16,831.92    |
| 61                           | AIR COOLER CHARGE                  | 1 \$ | 654.00                 |              |
| 62                           | A/C CONDENSER                      | 1 \$ | 683.00                 | \$ 546.00    |
| 63                           | A/C CONDENSER REFRIGERANT LINE     | 1 \$ | 186.00                 |              |
| 64                           | A/C CONDENSER REFRIGERANT LINE     | 1 \$ | 381.00                 |              |
| 65                           | A/C CONDENSER REFRIGERANT LINE     | 1 \$ | 277.00                 |              |
| 66                           | OUTSIDE TEMPERATURE SENSOR BRACKET | 1 \$ | 21.00                  | \$ 16.32     |
| 67                           | RADIATOR COOLANT                   | 1 \$ | 699.00                 | \$ 558.80    |
| 68                           | RADIATOR COOLANT FAN RING          | 1 \$ | 277.00                 | \$ 221.20    |
| 69                           | RADIATOR FAN CONTROL UNIT          | 1 \$ | 2,012.00               |              |
| 70                           | RADIATOR AIR GUIDE - LH / RH       | 2 \$ | 72.00                  | \$ 56.80     |
| 71                           | RADIATOR AIR GUIDE - LH / RH       | 2 \$ | 38.00                  | \$ 29.28     |
| 72                           | RADIATOR AIR GUIDE - UPPER         | 1 \$ | 19.00                  | \$ 14.64     |
| 73                           | RADIATOR AIR GUIDE - LOWER         | 1 \$ | 25.00                  |              |
| 74                           | READY- MIX COOLANT                 | 6 \$ | 297.00                 | \$ 237.12    |
| 75                           | INTAKE AIR DUCT - RH               | 1 \$ | 25.00                  | \$ 19.68     |
| 76                           | INTAKE AIR DUCT AIR GUIDE          | 1 \$ | 61.00                  | \$ 48.48     |
| 77                           | INTAKE AIR DUCT HOSE               | 1 \$ | 110.00                 | \$ 88.00     |
| 78                           | AIR FILTER                         | 1 \$ | 418.00                 |              |
| 79                           | FRONT FENDER TRIM - LH / RH        | 2 \$ | 342.00                 | \$ 136.40    |
| 80                           | FRONT DOOR TRIM - LH / RH          | 2 \$ | 342.00                 | \$ 136.40    |
| <b>SUB TOTAL SPARE PARTS</b> |                                    | :    | \$ 6,939.00            | \$ 18,941.04 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E**

|                             |                                             |            | DAMAGED PARTS & PRICES |              |
|-----------------------------|---------------------------------------------|------------|------------------------|--------------|
| S/N                         | PARTS DESCRIPTION                           | QTY        | S/NETT                 | REMARKS      |
|                             |                                             | <i>c/f</i> |                        | \$ 18,941.04 |
| 81                          | FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH | 2          | \$ 892.00              |              |
| 82                          | FRONT ROOF MOLDING - LH / RH                | 2          | \$ 1,412.00            | \$ 564.80    |
| 83                          | FRONT WATER DEFLECTOR STRIP - LH / RH       | 2          | \$ 150.00              |              |
| 84                          | FRONT FENDER PROTECTION FILM - LH / RH      | 2          | \$ 40.00               |              |
| 85                          | FRONT NO PLATE                              | S/N        | \$ 150.00              | \$ 150.00    |
| 86                          | SUNDRIES                                    |            | \$ 500.00              | \$ 43.44     |
| <b>TOTAL SPARE PARTS</b>    |                                             | :          | \$ 50,437.00           | \$ 19,699.28 |
| <b>TOTAL LABOUR CHARGES</b> |                                             | :          | \$ 19,724.00           | \$ 9,444.00  |
| <b>GRAND TOTAL</b>          |                                             | :          | \$ 70,161.00           | \$ 29,143.28 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-31/10/22