

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22008722/Uvy3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	20/09/2022	
			Code	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 1890R	Veh. Inspected	SMZ 9749Z	
	Policy No.	P10414246R02	Coverage (\$)	0.00	
	Claim No.	C10017312/CH	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	06/09/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180K (A)	c.c	1796	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	WDD2040462A244619	Colour	RED	
	Odometer	125046 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	PIRELLI	7 mm	
	L/H Front Tyre	225/45 R17	PIRELLI	7 mm	
	R/H Rear Tyre	225/45 R17	PIRELLI	7 mm	
	L/H Rear Tyre	225/45 R17	PIRELLI	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/09/2022	Inspection Date	06/09/2022	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: