



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 17/11/2022

### Survey details

Date of loss	12-07-22
Date of appointment	05-09-22
Date of survey	06-09-22
Location of survey	H S AUTOMOTIVE SERVICES

### Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	YP 6034H
Make and Model	ISUZU FSR34SUQCC
Date of registration	28-03-17
Excess	
Market Value	\$65,000.00
Parf Rebate	\$20,093.00
Nett Loss	\$44,907.00

### Repair details

Initial Estimate	
------------------	--

### Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	03 days (est)

### **Remarks:**

The estimated repair cost of the damaged vehicle is in the region of \$5,000.00-\$6,000.00