

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22008728/Tvy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	22/09/2022		
	ATTN: TEO KITTY			Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 4991Y	Veh. Inspected		SMG 928H	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04A7T	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		05/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CRV 1.5	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MRHRW1860KP000033	Colour		BLACK	
	Odometer	49245 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/60 R18	MICHELIN		6 mm	
	L/H Front Tyre	235/60 R18	MICHELIN		6 mm	
	R/H Rear Tyre	235/60 R18	MICHELIN		6 mm	
	L/H Rear Tyre	235/60 R18	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	31/08/2022	Inspect Date / 1	Γime	19/09/2022 (05:30 PM)	
	Survey held at	LUCK7WIN PTE LTD				
		51 UBI AVENUE 1 #01-11 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933				
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/ASM22008728/Tvy3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.