

Your Ref : DMPC2200396H

Date: 28th Sep 2022

Our Ref : CS/ICS22008743/Ucy3e2

M/s ECICS Ltd

10 Eunos Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKJ 3954U
ACCIDENT ON 03/09/2022**

Instruction was received to inspect the vehicle Reg. No. SKJ 3954U. The inspection was conducted on 07/09/2022 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit), Singapore 417883.

The following vehicle information was recorded:

| | |
|----------------------|-------------------------|
| Registration Number | : SKJ 3954U |
| Make/Model | : Audi A5 2.0 Quattro A |
| Year of Registration | : 2013 |
| Body Colour | : Black |
| Chassis Number | : WAUZZZ8T1CA018891 |
| Engine Capacity | : 1984 cc |

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

| | |
|------------------------------------|------------------------------|
| Market Value | S\$ 41,000.00 (est) |
| Less: LTA Reimbursement Value (RV) | (S\$ 36,464.00) |
| Nett Liability | <u>S\$ 4,536.00</u> ===== |

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.