

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22008746/GNY3M4**Date:** 06/10/2022**REFERENCE**

Insured/Claimant: MASWARI BIN MASTOR Policy No: DMPCSNW00037542201

Date of Loss: 04/09/2022

Nature of Claim: OD

Claim No: SNM22D206278/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX1991M	Engine No:	4B11BM7019
Make & Model:	mitsubishi EVO-10, 2.0 GSR SST (A)	Chassis No:	CZ4A0005870
Reg. Date:	19/02/2009 (Man. Year: 2008)	Odometer:	230747 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$148,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 ZR18	Rear Tyre Size:	245/40 ZR18
Front Left Side:	Sport Maxx 6 mm	Rear Left Side:	Sport Maxx 6 mm
Front Right Side:	Sport Maxx 6 mm	Rear Right Side:	Sport Maxx 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	3,500.00	-3,500.00	
Nett Amount (S\$)	0.00	-3,500.00	3,500.00	

INSPECTION

Date of Assignment:	05/09/2022	Present Location:	Car City Auto Centre Pte Ltd (HQ) Car City Auto Centre Pte Ltd (HQ)
Date Inspected:	06/09/2022	Inspected At:	Blk 9006 #01-198, Tampines Street 93 Singapore 528840
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$148,000.00
OMV :	\$ 36,154.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$ 31,335.00
COE Rebate (2) :	\$ 20,047.00
Total Rebate (1) + (2) = :	\$ 20,047.00

The total amount incurred will be Market Value \$148,000.00 minus Total Rebate \$20,047.00 = \$127,953.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Oct 2022)

Parts: M1-MPV MITSUBISHI EVO-10 2.0 GSR SST (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX1991M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >