



Your Ref SNM22D206278/C01

Date: 06<sup>th</sup> October 2022

Our Ref : CS/CTI22008746/Gny3m4

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJX 1991M  
ACCIDENT ON 04/09/2022**

Instruction was received to inspect the vehicle Reg. No. SJX 1991M. The inspection was conducted on 06/09/2022 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 Tampines Street 93, #01-198, Singapore 528840.

The following vehicle information was recorded:

Registration Number	: SJX 1991M
Make/Model	: Mitsubishi Evo-10 GSR 2.0 SST
Year of Registration	: 2009
Body Colour	: Silver
Chassis Number	: CZ4A0005870
Engine Capacity	: 1998 cc

The vehicle sustained damages at the front, rear portion, o/s, n/s body, undercarriage & rooftop. The chassis frame affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 148,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 20,047.00)
Nett Liability	<u>S\$ 127,953.00</u> =====

Vehicle Inspected By:



XING GUO QIANG  
M.MATAI, AMSAE-A  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.