



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE

6/9/2022

SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XE6051C Hino 700

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	FRONT BUMPER ASSY		2,659.00
2	1	FRONT HEADLAMP RH ASSY		1,859.00
3	1	FRONT HEADLAMP RH BRACKET		1,125.00
4	1	FRONT FOOT STEP LOWER GARNISH RH		789.00
5	1	FRONT FOOT STEP REFLECTOR		138.00
6	1	FOOT STEP STEEL PLATE		325.00
7	1	FOOT STEP EXTENSION RH		1,568.00

15% DIS

LABOUR & MISCELLANEOUS :

S/NO.	QTY	DESCRIPTION	AMOUNT S\$
1	1	To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary straighten front floor panel repair, reshape body dented panel in accordance to factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,200.00
2	1	To spray paint replaced/repainted body parts inclusive of preparatory works and painting materials	1,000.00
3	1	Wiring and bulb checking	150.00

WENG SHENG

KOH WENG SHENG

NAME, SIGNATURE, DATE SIGNED

3301.25

L/S - 2641
= 2650

Sten (LKK)
7/9/22, 10.10am

W R
L/S
hy AL y
3 Jy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: