

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Annualed to Federation internationale Des Experts Ell Automobile						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC22008757/Ecy3	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	06/09/2022	
				Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMQ 5108Y	Veh. Inspected		SHC 272X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1187352-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		06/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	05/09/2022	Inspection Date	е	06/09/2022	
	Survey held at	31 CORPORATION ROAD SINGAPORE 649825				
	Repairer	DING AUTOMOTIVE PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					