



### AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555

Co. Reg No. : 201500047H GST No. : 201500047H

Email : admin@autobacs.com.sg

TO	: NTUC (SLX6405H)	DATE	: 05-09-2022
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
<b>VEHICLE DETAILS</b>			
VEHICLE NO.	: SJP1509R	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged parts before resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>	
MODEL / MAKE	: TOYOTA ALLION		
CHASSIS NO.	: NZT260-3040673		
<b>ACCIDENT DETAIL</b>			
DATE	: 26-08-2022		
TIME	: 2135HRS		

**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT DOOR SIDE MIRROR RH	1	\$ 1,235.00	\$ 1,235.00
2	FRONT DOOR SIDE MIRROR COVER RH	1	\$ 105.00	\$ 105.00
TOTAL				\$ 1,340.00
LESS -25%				\$ 335.00
SUB TOTAL				\$ 1,005.00

Acknowledged by Repairer

Signature: *[Signature]*

Date: 07/09/22

750 BR  
~~645~~  
 70 BR  
 T 820  
 -12205  
 F=(615)

**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 200.00	/ 80	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 200.00	/ 80	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	α	

TOTAL \$ 480.00

Total 160

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 1,005.00 \$615  
 TOTAL LABOUR COST : \$ 480.00 \$160  
 TOTAL REPAIR COST : \$ 1,485.00

Mohamed Irfan  
 90097659

1 day L/S

After Repair survey

~~Cost~~ cost = \$775

-20% = 155

Total cost = \$600