



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA22008778/Ecy3	Date: 07/09/2022
			Code: AWA	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	XE 6903U
	Policy No.	BVFCB0007172215	Coverage (\$)	0.00
	Claim No.	NSV2200131/PC	Excess (\$)	2,500.00
	Assign From	GOH STELLA	Assign Date	07/09/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer		Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	22/08/2022	Inspection Date	07/09/2022
	Survey held at	24 JALAN BUROH S 619480		
	Repairer	SSB CRYOGENIC EQUIPMENT PTE LTD		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				