



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22008779/Uny3e2	
			Date: 01/11/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 7213B	Veh. Inspected	SND 151K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22002829MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	07/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5 QUATTRO (A)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WAUZZZ8T8AA061461	Colour	BLACK
	Odometer	184961 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35Z R19	GOODYEAR	6 mm
	L/H Front Tyre	255/35Z R19	GOODYEAR	6 mm
	R/H Rear Tyre	255/35Z R19	GOODYEAR	6 mm
	L/H Rear Tyre	255/35Z R19	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/09/2022	Inspection Date	07/09/2022
	Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	