



## Final Report

Estimate No. : **b1 63111**  
Date Estimated : **29/08/2022**  
Prepared By : **Yap Mee Key**

Page No. :

- **ESTIMATE REPAIR FOR** -  
**Tang Jingping**  
**75 Jurong East Street 13**  
**#04-02**

**Singapore 609652**

- **ACCOUNT** - **303**  
**MS First Capital Insurance Limited**  
**6 Raffles Quay**  
**#21-00**  
**Singapore 048580**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKV1711D	WBA2A32030V458541	31/08/2015	218iA AT	62516

DESCRIPTION	ORIGINAL PRICE		NETT
* To replace rear bumper and attachments, tailgate include knocking out dents caused by the accident	1,700.00	0.00	1,700.00
To respray tailgate and rear bumper.	1,972.00	0.00	1,972.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	504.00	0.00	504.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
To remove and install rear windscreen glass to facilitate repairs	545.00	0.00	545.00
To conduct water leak tests	71.00	0.00	71.00
Sundries	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	3.00	0.00	8.10
TRUNK LID	1,257.95	1.00	0.00	1,257.95
REAR BUMPER PANEL PRIMED (PDC)	1,050.55	1.00	0.00	1,050.55

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W





## Final Report

# EXPANDING NUT	1.00	2.00	0.00	2.00
REAR BUMPER CARRIER	490.70	1.00	0.00	490.70
SUPPORT	47.00	1.00	0.00	47.00
# RR BUMPER LH INNER SIDE GUIDE	163.55	1.00	0.00	163.55
# RR BUMPER RH INNER SIDE GUIDE	163.55	1.00	0.00	163.55
# PLUG BLACK D=5MM	0.95	7.00	0.00	6.65

### # SUPPLEMENTARY ITEMS

Total Labour :	5,390.00
Total Parts :	3,190.05
Total Labour & Parts :	8,580.05
Deduction for Excess :	
Total Repair Costs less Excess:	8,580.05
GST @7%:	600.60
Grand Total :	9,180.65

### Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

