



(Reg. No : 201824507D)

Address: 61 Woodlands Industrial Park E9, #01-19, Singapore 757047

Vehicle Number: FBS6020D

QTY	Description	Conditions	Repairer Price
1	COVER, SIDE 1 <i>X</i>	Damaged (Necessary)	\$ 105.00 <i>X nn</i>
1	COVER, SIDE 2 <i>X</i>	Damaged (Necessary)	\$ 105.00 <i>X</i>
1	COVER, SIDE 3 <i>cm</i>	Damaged (Necessary)	\$ 168.00 <i>-</i>
1	COVER, SIDE 4 <i>X</i>	Damaged (Necessary)	\$ 168.00 <i>X nn</i>
1	GRAPHIC 1 (Sticker Emblem) <i>nn</i>	(Necessary)	\$ 38.00 <i>-</i>
1	GRAPHIC 2 (Sticker Emblem) <i>nn</i>	(Necessary)	\$ 38.00 <i>-</i>
2	GRAPHIC 3 (Sticker Emblem) <i>nn</i>	(Necessary)	\$ 35.00 <i>-</i>
1	Steering Cone <i>nn</i>	(Necessary)	\$ 180.00 <i>-</i>
1	UNDER BRACKET COMP <i>X</i>	Damaged (Necessary)	\$ 350.00 <i>X nn</i>
1	FRONT FORK ASSY (L.H) <i>bt</i>	Damaged (Necessary)	\$ 300.00 <i>500</i>
1	FRONT FORK ASSY (R.H) <i>bt</i>	Damaged (Necessary)	\$ 300.00 <i>X nn</i>
1	HANDLE BAR COMP <i>X</i>	Damaged (Necessary)	\$ 160.00 <i>120</i>
1	FOOTREST BAR <i>bt</i>	Damaged (Necessary)	\$ 200.00 <i>X nn</i>
1	SHIFT PEDAL ASSY <i>X</i>	Damaged (Necessary)	\$ 80.00 <i>-</i>
1	PANEL, INNER 1 <i>cm</i>	Damaged (Necessary)	\$ 260.00 <i>-</i>
1	PANEL, FRONT COVER <i>cm</i>	Damaged (Necessary)	\$ 185.00 <i>-</i>
1	PANEL, INNER 2 <i>cm</i>	Damaged (Necessary)	\$ 220.00 <i>-</i>
1	COVER 3 (PANEL REAR) <i>scd</i>	Damaged (Necessary)	\$ 95.00 <i>-</i>
1	COVER (CENTER CONSOLE) <i>cm</i>	Damaged (Necessary)	\$ 90.00 <i>-</i>
1	PANEL 1 (FAIRING L/H) <i>cm</i>	Damaged (Necessary)	\$ 125.00 <i>-</i>
1	COVER, UNDER FAIRING (L/H) <i>X</i>	Damaged (Necessary)	\$ 80.00 <i>X nn</i>
1	PANEL 2 (FAIRING R/H) <i>X</i>	Damaged (Necessary)	\$ 125.00 <i>X nn</i>
1	AIR GUIDE R/H (UNDER INNER FAIRING) <i>X</i>	(Necessary)	\$ 68.00 <i>X nn</i>
1	AIR GUIDE L/H (UNDER INNER FAIRING) <i>X</i>	(Necessary)	\$ 68.00 <i>X nn</i>
1	COVER, UNDER FARING (R/H) <i>X</i>	Damaged (Necessary)	\$ 80.00 <i>X nn</i>
1	COVER, UNDER FARING (BOTTOM) <i>X</i>	(Necessary)	\$ 85.00 <i>X nn</i>
1	FENDER, INNER <i>scd</i>	(Necessary)	\$ 98.00 <i>-</i>
1	COVER 1 (CENTER FAIRING) L/H <i>scd</i>	Damaged (Necessary)	\$ 145.00 <i>-</i>
1	COVER 2 (CENTER FAIRING) R/H <i>X</i>	Damaged (Necessary)	\$ 145.00 <i>X nn</i>



1000

7527.00	parts -	2801
		10%
		<u>2520.90</u>

$$\begin{array}{r} 2520.90 \\ 284.00 \\ 390.00 \\ \hline 3194.90 \\ 20\% \\ 2555.92 \end{array}$$

115.82,550

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: