



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22008808/Rvy3m4 Date: 31/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9575Z	Veh. Inspected	FBS 6020D
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M04A2L	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	07/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	RLCUG1610MY001064	Colour	GREY
	Odometer	31415 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	BRIDGESTONE	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/80-17	BRIDGESTONE	3 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/08/2022	Inspection Date	07/09/2022
	Survey held at	THCYCLE PTE LTD 61 WOODLANDS INDUSTRIAL PARK E9, #01-19, E9 PREMIUM, SINGAPORE 757047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	