



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22008832/Any3q2 Date: 04/10/2022  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLN 1559H	Veh. Inspected	SGZ 35E	
Policy No.	P10545914R01	Coverage (\$)	0.00	
Claim No.	C10017384/JT	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	08/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PREVIA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTEGD52M20A019445	Colour	SILVER	
Odometer	501159 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	TOYO	6 mm	
L/H Front Tyre	235/50 R18	TOYO	6 mm	
R/H Rear Tyre	235/50 R18	TOYO	6 mm	
L/H Rear Tyre	235/50 R18	TOYO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/09/2022	Inspection Date	13/09/2022	
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	