



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM22008837/Eqy3m4

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

Date: 28/10/2022

ATTN: ANG YVONNE

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 7777K	Veh. Inspected	GBF 8047H
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S2M04AKG	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	08/09/2022


2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDY2318026558	Colour	SILVER
Odometer	125694 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195R15C	YOKOHAMA	4 mm
L/H Front Tyre	195R15C	YOKOHAMA	4 mm
R/H Rear Tyre	195R15C	YOKOHAMA	4 mm
L/H Rear Tyre	195R15C	YOKOHAMA	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.	
---	---

5. General Information

Accident Date	21/08/2022	Inspect Date / Time	14/09/2022 (02:33 PM)
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/ASM22008837/Eqy3m4

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.