

ASS. REC. BY:

REF:

A/G/ 22 008840/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SLK 2821 J Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle Wagon 1498

Colour

M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading

120732 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK8 1007842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

S mm

Rear

R/Bal.

S mm

L/Bal.

S mm

L/Bal.

S mm

D.O.A.

3/9/22

D.O.I.

7/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/9 21:00 @ 3700d Cabin

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06649

Vehicle Insured : SDW6188J
Accident Date : 03-Sep-2022

Date : 05-Sep-2022

Our Ref : 022141 (AIG) / CHAN

PAGE : 1

RA MACK CAR RENTALS
BLK 251 COMPASSVALE STREET
#10-31
Singapore 540251

Not wither
L1 Rep @ 3700hr
Recovery After Paint
5days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE SLK2821J

1 pc	Tail gate	1,193.00	✓
2 pcs	Tail gate glass side moulding @ S\$ 56.50	113.00	✓
1 pc	Tail gate glass lower moulding	86.20	✓
1 pc	Tail gate "SHUTTLE" emblem	55.00	✓
1 pc	Tail gate rubber	168.00	50%sn
1 pc	Tail gate inner lock	256.00	✓
1 pc	Tail gate open pocket	25.00	✓
1 pc	Rear end panel	560.00	✓
1 pc	End panel top garnish	155.50	✓
1 pc	Rear bumper fascia	1,150.60	✓
1 pc	Rear o/s bumper reflector	51.50	X
1 pc	Rr o/s bumper reflector cover	45.00	X
1 pc	O/s bumper reflector bracket	56.50	X

3,915.30

Less 20% : 783.06

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip (set)
- 1 pc Rear bumper reverse sensor(set)

3,132.24 40%sn
60.00 sn
40.00 sn ✓
300.00 sn
200%sn

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 120%

To remove roof lining, front and
rear seats, trim board and carpet

120.00 60%

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SDW6188J

Page : 2

To apply undersealing

60.00 ✓

To putty and spray replaced parts

600.00 ✓

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *book*

Total : S\$ 5,162.24

=====

Singapore Dollars Five Thousand One Hundred and
Sixty Two and Cents Twenty Four Only