



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM22008849/Uvy3m4 Date: 16/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLQ 3674D	Veh. Inspected	SMZ 2199G
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M04ALM	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	08/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050402R317054	Colour	SILVER
	Odometer	48757 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
	L/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm
	L/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/09/2022	Inspection Date	12/09/2022
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	