



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

COOMA & RAI

8 ROBINSON ROAD #10-00 ASO BUILDING
SINGAPORE 048544

Ref: CS/LAW22008861/Kny3e2

Date: 10/11/2022

Code: L049

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBG 4715J	Veh. Inspected	SLT 8181K
Policy No.		Coverage (\$)	0.00
Claim No.	MPR/215542/LA9	Excess (\$)	0.00
Assign From	f. DANIEL GOH	Assign Date	08/09/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PREVIA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTEGD56M107152902	Colour	METALLIC GREY
Odometer	89143 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	02/06/2021	Inspection Date	13/09/2022
Survey held at	JP CONCEPTZ PTE LTD 160 SIN MING DRIVE #07-11 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------