



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 8181K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION JAPAN
MODEL ACB50R-GF XSK 2362 mL
ENGINE 2AZ-FE
FRAME No. JTEGD56M107152902
COLOR TRIM PLANT OPTION
1H4 ED20 C25
TWE/ABLE K112 -03A 694