

## Shiau Chan (LKKAuto)

---

**From:** Finalization  
**Sent:** Wednesday, 21 December 2022 2:30 PM  
**To:** joel@falconair.com.sg  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** SKX3826H - Finalize  
**Attachments:** Supp.pdf; SKX3826H main estimate.pdf

Hi Joel,

We will be advising our principal for the costs of repairs in \$9150.00 (L/S, before GST), 7 days. Subject to their approval.

Thanks.  
Best Regards,  
Case Handler

### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** joel@falconair.com.sg <joel@falconair.com.sg>  
**Sent:** Wednesday, December 21, 2022 11:26 AM  
**To:** Finalization <finalization@lkkauto.com>  
**Subject:** FW: SKX3826H

Dear Sir/Mdm,

Pls assist to finalise this case.

Thanks and regards,  
Joel Ng  
Falcon-Air Auto Services Pte Ltd (Tampines)  
Tel:67897997

---

**From:** joel@falconair.com.sg <joel@falconair.com.sg>  
**Sent:** Thursday, 13 October 2022 4:51 pm  
**To:** 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>  
**Subject:** FW: SKX3826H

Dear Guoqiang,

Pls see attached finalised report, supp estimate and after paint photos.

I would like to finalise this case base on LS basis as follows.

PS:I forgot to take photo of the diagnostic scanner, but I definitely have to diagnose and clear code. Replacement of aircleaner have to take unplug MAF sensor.

Parts(10%)-\$7925/-(\$8717.50/-)  
S/N-\$205/-  
Labour-\$2470/-  
Supp(10%)-\$93/-(\$102.30/-)

Total-\$11494.80/-  
Less LS 20%-\$9195.84/-

Rd off-\$9200/-  
7 days.

Pls confirm.

Thanks and regards,  
Joel Ng  
Falcon-Air Auto Services Pte Ltd (Tampines)  
[Tel:67897997](tel:67897997)