

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 12 September 2022 1:48 PM
To: joshua@falconair.com.sg
Cc: SUR
Subject: ALLIANZ-OD SKX 3826H DOA: 07/09/2022

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SKX 3826H at repair cost on Lump Sum basis (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)