



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interr	nationale Des Experts En A	Automol	oile	
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22008877/Gny3	
	8 SHENTON WAY	I	Date:	09/09/2022		
	AXA TOWERSING	APORE 068811	,	Cada	ASM	
1.		Policy Particula	ars :- (THIRD PARTY (	CLAIM		
	Insured Veh. SHA 9497R Veh. Inspected			OLAIM	FBS 9362Y	
	Policy No.	-	Coverage (\$)		0.00	
	Claim No.	S2M04AOH			0.00	
			Excess (\$)			
	Assign From	TEO KITTY	Assign Date		09/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	-	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour		_	
	Odometer	-	Steering	Steering		
	Brakes		Modification			
	General				-	
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
J.	Accident Date	07/09/2022			09/09/2022	
			Inspection Date	;	03/03/2022	
	Survey held at					
		282 MACPHERSON ROAD SINGAPORE 348607				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					