



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22008911/Eny3e2	
			Date: 07/12/2022	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLQ 1132P
	Policy No.	DHOM120042751901	Coverage (\$)	0.00
	Claim No.	M12D19502209	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	12/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X1	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBAHS120005J97008	Colour	BLUE
	Odometer	30058 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	PIRELLI	4 mm
	L/H Front Tyre	225/50 R18	PIRELLI	4 mm
	R/H Rear Tyre	225/50 R18	PIRELLI	4 mm
	L/H Rear Tyre	225/50 R18	PIRELLI	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/09/2022	Inspection Date	12/09/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$95,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		22 Working Days	