

FormTeam Consultancy Pte Ltd

Vehicle No: YM 9547R

Workshop: Hong Huat Mtr Svcs

Accident Date: 25 March 2019

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868


Tel : (65) 6509 1788
Fax : (65) 6509 6221


Email: motorsurvey@fta.com.sg
www.fta.com.sg

Co. Reg No: 200819280D

GST Reg. No: 200819280D















BARRIER SYSTEMS INC

To ensure that this safety product will function properly, it should be located, installed, and maintained following the recommendations given in the product manual and drawings supplied with the product. Installers and users should read warnings and cautions. For Customer Service, contact BARRIER SYSTEMS, INC. at 707-374-6800 or 150 River Rd, Rio Vista, CA 94571. www.barriersystemsinc.com

PART # 5-21112
SALE WORK ORDER # 5-4637
SERIAL # 4-2107
DATE 5/14/12
SHIP DATE 5/17/12

BARRIER SYSTEMS INC

To ensure that this safety product will function properly, it should be located, installed, and maintained following the recommendations given in the product manual and drawings supplied with the product. Installers and users should read warnings and cautions. For Customer Service, contact BARRIER SYSTEMS, INC. at 707-374-6800 or 150 River Rd, Rio Vista, CA 94571. www.barriersystemsinc.com

PART # 5-21112
SALE WORK ORDER # 5-4637
SERIAL # 4-2107
DATE 5/14/12
SHIP DATE 5/17/12

CHASSIS NO : FM65FMB00038 
UNLADEN WT : 7700 **KG**
MAX LADEN WT : 16000 **KG**
PASSENGER CAP : 1 DRIVER 2 **OTHER**
TYRE SIZE : (F) 11R22.5-16PR
(R) 11R22.5-16PR











