

 Delete

 Archive

 Report ▾

 Reply

 Reply all

 Forward ▾

 Read / Unre

Pre-Repair Survey Report & Invoice of Vehicle SMZ 1022P Ref: CMTD2203168/SYH

RS

Renee Sia (LKK Auto)

To: Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: 'Claims - Motor Survey' <MotorSurvey@sompo.com.sg>; SUR



Tue 11/29/2022 5:06 PM



LKKPhoto.pdf
284 KB



LKKPreRepairInspection.pdf
540 KB



Resurvey Photo-1.pdf
236 KB



Resurvey Photo-2.pdf
117 KB



SMO-LKKInvoice-AC2207362...
64 KB



 5 attachments (1 MB)  Download all

Dear Shiang Yi,

Enclose Pre-Repair Survey Report of SMZ 1022P.

Thank you.

Best Regards,

Renee | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933



Reply



Reply all



Forward