



ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Ref. No
Date of Loss: 01/09/2022
Driveable?

Vehicle Reg. Date: 16/03/2015

Chassis No: YV1F540LDF2348244

Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

Parts	14,662.50
Miscellaneous Items	40.00
Labour	830.00
Paintwork Labour	680.00
Towing	0.00
Gross Total (\$\$)	16,212.50
+ GST 7.00% (\$\$)	1,134.88
Nett Amount (\$\$)	17,347.38

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2022)
Parts: 143 VOLVO S60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKR8773A/09/09/2022 17:55
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	nn x *1,250.00 F
2	1		*FRONT BONNET LOCK RH	0.00	0.00	nn x *150.00 F
3	1		*FRONT BONNET LOCK LH	0.00	0.00	nn x *150.00 F
4	1		*FRONT SUPPORT PANEL	0.00	0.00	nn x *2,200.00 F
5	1		*FRONT GRILLE	0.00	0.00	wa / *420.00 F
6	1		*FRONT BUMPER	1500	0.00	de / *2,300.00 F
7	1		*FRONT BUMPER FOAM	0.00	0.00	nn x *230.00 F
8	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	nn x *750.00 F
9	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	nn x *100.00 F
10	1		*FRONT HEADLAMP RH	0.00	0.00	nn x *2,600.00 F
11	1		*FRONT HEADLAMP LH	0.00	0.00	nn x *2,600.00 F
Sub Total S\$)						12,750.00
+ Margin on L.N items 15.00% S\$)						1,912.50
Total Parts S\$)						14,662.50

F=Franchise part.

Kan Fook Sing Motor Workshop/SKR8773A/09/09/2022 17:55. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	40.00
Sub Total (S\$) <i>bf</i>			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New <i>250</i>	680.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New <i>30?</i>	50.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New <i>X</i>	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New <i>250</i>	680.00
Gross Labour Cost (S\$)			1,510.00

Kan Fook Sing Motor Workshop/SKR8773A/09/09/2022 17:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufai 97495749
'WP' 23/9/22 3pm
taufai @khantowm
2 days - 3 days
Resury before paint
To check 4/5 or 1/1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: